

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

*Amended Report*

|                                                   |                                                                        |
|---------------------------------------------------|------------------------------------------------------------------------|
| WELL API NO.                                      | 30-025-24089                                                           |
| 5. Indicate Type of Lease                         | STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil / Gas Lease No.                      | 858150                                                                 |
| 7. Lease Name or Unit Agreement Name              | WEST VACUUM UNIT                                                       |
| 8. Well No.                                       | 126                                                                    |
| 9. Pool Name or Wildcat                           | VACUUM GRAYBURG SAN ANDRES                                             |
| 10. Elevation (Show whether DF, RKB, RT,GR, etc.) |                                                                        |

SUNDRY NOTICES AND REPORTS ON WELL  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

|                        |                                                                                                                                                                                            |
|------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1. Type of Well:       | OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>                                                                              |
| 2. Name of Operator    | TEXACO EXPLORATION & PRODUCTION INC.                                                                                                                                                       |
| 3. Address of Operator | 205 E. Bender, HOBBS, NM 88240                                                                                                                                                             |
| 4. Well Location       | Unit Letter <u>L</u> : 1980 Feet From The <u>SOUTH</u> Line and <u>490</u> Feet From The <u>WEST</u> Line<br>Section <u>34</u> Township <u>17S</u> Range <u>34E</u> NMPM <u>LEA</u> COUNTY |

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

|                       |                          |                  |                          |
|-----------------------|--------------------------|------------------|--------------------------|
| PERFORM REMEDIAL WORK | <input type="checkbox"/> | PLUG AND ABANDON | <input type="checkbox"/> |
| TEMPORARILY ABANDON   | <input type="checkbox"/> | CHANGE PLANS     | <input type="checkbox"/> |
| PULL OR ALTER CASING  | <input type="checkbox"/> |                  |                          |
| OTHER:                | <input type="checkbox"/> |                  |                          |

SUBSEQUENT REPORT OF:

|                             |                                     |                      |                          |
|-----------------------------|-------------------------------------|----------------------|--------------------------|
| REMEDIAL WORK               | <input checked="" type="checkbox"/> | ALTERING CASING      | <input type="checkbox"/> |
| COMMENCE DRILLING OPERATION | <input type="checkbox"/>            | PLUG AND ABANDONMENT | <input type="checkbox"/> |
| CASING TEST AND CEMENT JOB  | <input type="checkbox"/>            |                      |                          |
| OTHER:                      | <input type="checkbox"/>            |                      |                          |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-01-98: MIRU. NDWH. NUBOP. TIH W/BIT, CSG SCRAPER. PU 182 JTS 2 7/8" TBG & TIH TO 5835'.  
 4-02-98: TIH W/GAUGE RING, JUNK BASKET TO 8000'. TIH W/CIBP & SET @ 7650'. LOAD CSG W/140 BBLS & TEST CSG & PLUG TO 500#-OK. TIH W/TDT LOG TOOL, LOG FR 5800-3000'. TIH W/DUMP BAILER & CAP CIBP W/35' IN 2 RUNS. NEW PBTD @ 7615'.  
 4-06-98: TIH W/CSG GUN & PERF 4780-4802', 4864-4882' W/4 JSPF 120 DEG PHASING, 40', 160', 42 HOLES.  
 4-07-98: TIH W/PKR, SN, 148 JTS 2 7/8" TBG. TEST TO 5000#. PSA 4735'. LOAD & TEST BACKSIDE TO 500#-OK. ACIDIZE 4780-4882' W/6000 GALS 15% NEFE HCL & 800# RK SLT. BLED WELL DN & RECVD 39 BLW. SWABBING.  
 4-08-98: REL PKR.  
 4-09-98: TIH W/CSG GUN. PERF 4640-4660' W/2 JSPF, 120 DEG PHASING, 20', 40-42" HOLES. TIH W/RBP & PKR, & SN ON 2 7/8" TBG. SET RBP @ 4729'. SET PKR & TEST RBP TO 1000#-OK. PULL UP & SET PKR @ 4602'. LOAD & TEST CSG TO 500#-OK.  
 4-10-98: BLED DN IN 5 MIN. PRESS CSG TO 500#. ACIDIE 4640-4660' W/3000 GALS 15% NEFE HCL & 500# RK SLT.  
 4-13-98: OPEN W3ELL TO TANK. REL PKR & TIH. LATCH ONTO RBP.  
 4-14-98: TIH W/CSG GUN. PERF 4508-4545, 4450-4498. TIH W/RBP, PKR, SN, & 2 7/8" TBG TO 4608'. SET RBP & TEST TO 1000#-OK. PULL PKIR TO 4416' & SET. PSI CSG TO 500#-OK.  
 4-15-98: SPOT ACID TO PKR. PSI CSG TO 500#-OK. ACIDIE 4450-4545' W/7000 GALS 15% HCL NEFE & 1000# RK SLT. SWAB.  
 4-16/20-98: SWAB. REL PKR. TIH & WSH 20' SALT OFF RBP @ 4608'. REL RBP. TIH W/CIBP & PKR ON 2 3/8" TBG. SET CIBP @ 4580'. PSA 4575'. TEST CIBP TO 1000#-OK. REL PKR.  
 4-21-98: TIH W/FAC PKR, SN, & 3 1/2" FRAC TBG. TEST TBG TO 8000#. PSA 4339'. TEST CSG TO 500#-OK.  
 4-23-98: FRAC 4450-4545' W/10,248 GALS 30# X/LNKD GEL. PSI TO 10,000.  
 4-24-98: FLOW WELL TO TANK. TIH W/CHEM CUTTER, CUT TBG @ 4320'.  
 4-27-98: RAN OVER SHOT, GRAPPLE, BMPR SUB, JARS, DC'S 2 7/8" TBG. CATCH FSH @ 4320'. JAR.  
 4-28-98: JAR LOOSE. TIH W/SHOE, JARS & TBG. TAG @ 4340'. CUT ON PKR. PULL TO 4317'.  
 4-29-98: LOWERED TBG TO 4340'. TAG PKR @ 4340'. TIH W/SHOE, JARS ON TBG. TAG @ 4516'. C/O TO 4580'.  
 5-01-98: MA @ 4556', SN @ 4521', TAC @ 4232'. NDBOP & SET TAC. NUWH. TIH W/GAS ANCHOR, PMP. TEST TO 500#-OK. RIG DOWN.  
 6-07-98: ON 24 HR OPT. PUMPED 4 BO, 20 BW, & 0 MCF. FINAL REPORT  
change name from North Vacuum Abo West Unit #25 to West Vacuum Unit #126

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 2/22/99  
 TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE PETROLEUM ENGINEER DATE \_\_\_\_\_  
 CONDITIONS OF APPROVAL, IF ANY:

*Handwritten signature/initials*