

JOB SUMMARY: RUS4X NUBOPX string out of PKRX POHX
PU Lockset PKRX TIHX Leave out 18' SUBSX Set
PKRX Test OK X CIRC PKR Fluid X NUHX Run
CHART For Completion: RDS4