O. C COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old
NTAFE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
E		211021149 14-03
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE	+	State X Fee
OPERATOR		5. State Oil & Gas Lease No.
		K-6023
(DO NOT USE THIS FORM	UNDRY NOTICES AND REPORTS ON WELLS FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. PELICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL GAS WELL WELL	OTHER-	7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
TEXACO Inc.		New Mexico 'DN' State Co
3. Address of Operator		9. Well No.
P.O. Box 728	, Hobbs, New Mexico 88240	1
4. Location of Well		10. Field and Pool, or Wildcat
JUNIT LETTER J	1980 FEET FROM THE South LINE AND 1980 FEET FROM	Vacuum Morrow Gas
UNIT LEIVER		
THE East LINE	, section <u>18</u> township <u>17</u> S range <u>35</u> E nmpm.	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
ΛΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙ	3991' (GR)	Lea ()))))
16. C	neck Appropriate Box To Indicate Nature of Notice, Report or Oth	er Data
	OF INTENTION TO: SUBSEQUENT	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JQB	
	OTHER Perforate	E Acidíze X
OTHER		

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

۶.

- 1. Perforate 5-1/2" casing w/2 JSPI @12040-46 and 12051-55'.
- 2. Acidize perforations 11550-12066' w/10,000 gal 7-1/2% MS acid & 1,000 SCF N2/bbls. of acid in 8 stages separated w/175 ball sealers. Flush w/35 bbls 2% KCL water and N2.
- 3. Flow. Ran swab to 11,000⁺.
- 4. Workover unsuccessful. Subject well TR-NG (To be Reconditioned, Natural Gas).

IGNED	Assistant District Superintendent	7-9-74
PPROVED BY	T T L E) : date