



GUIDE TO DRILLING LOGS AND TEST PRESSURE CHARTS



- A. Initial Hyd. Mud
- B. Initial Shut-in
- C. Initial Flow
- D. Final Flow
- E. Final Shut-in
- F. Final Hyd. Mud

The following points are either fluctuating pressures or points indicating other packer settings, (testing different zones).

- A-1, A-2, A-3, etc. Initial Hyd. Pressures
- B-1, B-2, B-3, etc. Subsequent Shut-in Pressures
- C-1, C-2, C-3, etc. Flowing Pressures
- D-1, D-2, D-3, etc. Subsequent Final Flow Pressures
- E-1, E-2, E-3, etc. Subsequent Final Shut-in Pressures
- F-1, F-2, F-3, etc. Final Hyd. Mud Pressures
- Z — Special pressure points such as pumping pressure recorded for formation breakdown.



LOG NO. 1000

LOG NO. 1000

DATE 10/1/54

REPORT REQUESTED

6400

51

