

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry		7. Unit Agreement Name
2. Name of Operator Harding Oil Company		8. Farm or Lease Name Shipp
3. Address of Operator 408 Carillon Tower West, 13601 Preston Rd., Dallas, Texas		9. Well No. 6
4. Location of Well UNIT LETTER <u>G</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>10</u> TOWNSHIP <u>17S</u> RANGE <u>37E</u> NMPM.		10. Field and Pool, or Wildcat Humble City-Undesig
15. Elevation (Show whether DF, RT, GR, etc.) 3754' GL		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-27-73 - 40 sx cement plug 11,520-11,410 Top Atoka
40 sx cement plug 11,340-11,240 Top Strawn
40 sx cement plug 9740-9640 Top Wolfcamp
40 sx cement plug 8010-7910 Top Yeso
40 sx cement plug 6700-6600 Top Glorieta
40 sx cement plug 4800- in and out 8-5/8" casing
6-30-73 - Move off drilling rig
8- 5-73 - Move in casing pulling unit
8- 6-73 - Cut and recover 1224' 8-5/8" casing
55 sx cement plug 1209 - in and out 8-5/8" casing
55 sx cement plug 413 - in and out 13-3/8" casing
10 sx cement plug in top of 13-3/8" casing
Put well location marker in place
10-13-73 Pick up caliche and level pits

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>J. D. Buckner Jr.</u>	TITLE <u>Vice President</u>	DATE <u>10-16-73</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u>Secretary</u>	DATE <u>10-16-73</u>
CONDITIONS OF APPROVAL, IF ANY:		