\bot		•		
Submit 3 Copies	State of New Mexico		Form C-103	
to Appropriate District Office	Energy, Minerals and Natural Re	sources Department	Revised 1-1-89	
DISTRICT I	DISTRICT I P.O. Box 1980, Hobbe, NM \$4240 DISTRICT II OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088			
P.O. Box 1980, Hobbs, NM \$5240			WELL AP! NO.	
DISTRICT II			30-025-24638	
P.O. Drawer DD, Artesia, NM \$1210		S. Indicate Type of Lease STATE X FEE		
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM \$7410			6. State Oil & Ges Lesse No.	
			B-2131	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PLEMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lasse Name or Unit Agreement Name	
1. Type of Well: OL OL GAS WILL X WILL	onan		East Gb-SA Unit Tract 2648	
2. Name of Operator			8. Well No.	
Phillips Petroleum	Company		126	
1. Address of Operator 4001 Penbrook St.,	Odessa, Texas 79762		9. Poci seme or Wildow Vacuum Gb/SA	
4. Well Location			· · · · · · · · · · · · · · · · · · ·	
	90 Fost From The South	Line and33	0	
Section 26	Township 17-S Ha	35-E		
	1000 Miles (Show whether		NMPM Lea County	
	391	3 RKB		
11. Check	Appropriate Box to Indicate I	Nature of Notice, R.	eport, or Other Data	
NOTICE OF IN			SEQUENT REPORT OF:	
		REMEDIAL WORK		
PULL OR ALTER CASING				
OTHER: Deepen Well 125'				
12. Describe Proposed or Completed Operations (Clearly state all pertinent detaile, and give particent dates, including animated date of starting any proposed				
work) SEE RULE 1105.			and an intervention of her and the bud have	
Stimulate and test new zone. Perforate and acidize upper San Andres pay. Install				
new production equipment. 1. MIRU reverse unit, power swivel, and steel mud pits. RIH w/4-3/4" bit, 3-1/2"				
1. MIRU reverse unit	C, power swivel, and R ^m that Drill up CTE	Steel mud pit	Clean out to PBTD of 4672'.	
			rilled/milled up during the	
TA operations.	After ensuring hole i	s clean, deep	en well 125' to 4825' using	
produced water for drilling fluid. Circulate hole clean. COOH.				
 RIH w/5-1/2" 15.5# casing scraper to 4680'. POOH. RIH w/RTTS-type packer and set same at 4650'. Swab 4 hrs. 				
 RIH w/RTTS-type packer and set same at 4650'. Swab 4 hrs. Acidize San Andres formation from 4700'-4825' with a total of 4000 gallons of 				
15% NEFe acid containing LST agent, clay stabilizer and 5% Techni-Wet 425				
15% NEFe acid com	es formation from 470 ntaining LST agent, c	0'-4825' with lay stabilize	a total of 4000 gallons of	
(3.5 drums). Div	es formation from 470 ntaining LST agent, c vert with 3000 lbs ro	0'-4825' with lay stabilize	a total of 4000 gallons of	
(3.5 drums). Div 5. Swab. COOH w/tb	es formation from 470 ntaining LST agent, c vert with 3000 lbs rc g and packer.	0'-4825' with lay stabilize ck salt.	a total of 4000 gallons of r and 5% Techni-Wet 425	
(3.5 drums). Div 5. Swab. COOH w/tb 6. Perforate the 5-	es formation from 470 ntaining LST agent, c vert with 3000 lbs rc g and packer. 1/2" casing at the fo (OVER	0'-4825' with lay stabilize ck salt.	a total of 4000 gallons of	
(3.5 drums). Div 5. Swab. COOH w/tb 6. Perforate the 5-	es formation from 470 ntaining LST agent, c vert with 3000 lbs rc g and packer. 1/2" casing at the fo (OVEL w and complete to be bet of my increases and	0'-4825' with lay stabilize ck salt. llowing depth	a total of 4000 gallons of r and 5% Techni-Wet 425 s using 4" casing guns	
(3.5 drums). Div 5. Swab. COOH w/tb 6. Perforate the 5-3 I hardy outly hat he information damy is the	es formation from 470 ntaining LST agent, c vert with 3000 lbs rc g and packer. 1/2" casing at the fo (OVEL w and complete to be bet of my increases and	0'-4825' with lay stabilize ck salt. llowing depth	a total of 4000 gallons of r and 5% Techni-Wet 425	
(3.5 drums). Div 5. Swab. COOH w/tbs 6. Perforate the 5-3 I hereby coeffy that the information stores is the sconarum A.M.	es formation from 470 ntaining LST agent, c vert with 3000 lbs rc g and packer. 1/2" casing at the fo (OVEL w and complete to be bet of my increases and	0'-4825' with lay stabilize ck salt. llowing depth	a total of 4000 gallons of r and 5% Techni-Wet 425 s using 4" casing guns	
(3.5 drums). Div 5. Swab. COOH w/tbo 6. Perforate the 5- I have softy but to information down is to sconarum A. M. S TYPE OR PERIT HAME L. M. S	es formation from 470 ntaining LST agent, c vert with 3000 lbs rc g and packer. 1/2" casing at the fo (OVER us and complete to best of my incomings and configure and Sanders	0'-4825' with lay stabilize ck salt. llowing depth	a total of 4000 gallons of r and 5% Techni-Wet 425 s using 4" casing guns & Proration DATE 10-25-91 TELEPHONE MO.	
(3.5 drums). Div 5. Swab. COOH w/tbs 6. Perforate the 5-3 I hereby coeffy that the information stores is the SIGNATURE AND TYPE OR PREMY NAME L. M. S (This space for State UniORIGINAL Second	es formation from 470 mtaining LST agent, c vert with 3000 lbs rc g and packer. 1/2" casing at the fo (OVER and complete to bet of sy booledge and Sanders NEO BY JERBY DEXTON	0'-4825' with lay stabilize ck salt. llowing depth	a total of 4000 gallons of r and 5% Techni-Wet 425 s using 4" casing guns & Proration 10-25-91	
(3.5 drums). Div 5. Swab. COOH w/tbs 6. Perforate the 5-3 I have outly that the information stores is the SOMATURE AND THE L. M. S (This space for State UniORIGINAL Second	es formation from 470 ntaining LST agent, c vert with 3000 lbs rc g and packer. 1/2" casing at the fo (OVER w and complete to best of my incomings and configure and Sanders	0'-4825' with lay stabilize ock salt. llowing depth l win. Supv., Reg.	a total of 4000 gallons of r and 5% Techni-Wet 425 s using 4" casing guns & Proration DATE 10-25-91 TELEPHONE MO.	

loaded with two 23 gram shots/ft. Correlate to GR on Dresser EPILOG dated 1-17-74.

DEPTHS	FEET	<u>Shots</u>
4460-4478'	18	36
4515-4564'	49	98
4573-4577'	4	8
4608-4617'	9	18
4624-4630'	6	12
	86	172

- 7. RIH w/RTTS-type packer on 2-7/8" tubing. Set packer at 4350'. Swab test perfs for at least four hours.
- Acidize San Andres perfs from 4440'-4630' with a total of 4500 gallons of 15% NEFe acid containing LST agent, clay stabilizer and 5% Techni-Wet 425 (4 drums). Divert with 6000 lbs. rock salt (incl. excess).
- 9. Swab. COOH w/tbg and tools.
- 10. RIH w/48 HP motor. seal. rotary gas separator. 188 Stage FC650 Centrilift pump. #4 round power cable and 2-7/8" J-55 production tbg. Set motor at ± 4350'.

ž

the weeks

11. Return well to operation.

- · · ·

RECEIVED

5 43

OCT 2 9 1991 COD HOBBS OFFICE

regpro/jcock/bsa.1