Office Danse Mills 1	of New Mexico		Form C-10	
District I Energy, Mineral	s and Natural Resources		Revised March 25, 199	
1625 N. French Dr., Hobbs, NM 87240 District II		WELL API NO.		
811 South First, Artesia, NM 87210 OIL CONSEI	OIL CONSERVATION DIVISION		30-025-24643	
District III 2040	2040 South Pacheco		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 Santa District IV	Santa Fe, NM 87505		STATE X FEE	
2040 South Pacheco, Santa Fe, NM 87505		6. State Oil & Gas B-2519	Lease No.	
SUNDRY NOTICES AND REPORT	S ON WELLS	7 Lease Name or	Unit Agreement Name:	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" PROPOSALS.)	O DEEPEN OR PLUG BACK TO	) A	omt Agreement Name.	
1. Type of Well: Oil Well X Gas Well Other		SANIA FE		
2. Name of Operator		8. Well No.		
Phillips Petroleum Company				
. Address of Operator			9. Pool name or Wildcat	
4001 Penbrook Street Odessa, TX 79762			1	
4. Well Location		VACUUM (YATES)		
Unit Letter <u>G</u> : 1650 feet from t	heNORTH line and	2310 feet fro:	n the <b>EAS</b> T line	
Section 34 Township	17S Range 35E		County LEA	
10. Elevation (Sho	w whether DR, RKB, RT, G		2888888888888888	
	3911' GL, 3921' RKB			
11. Check Appropriate Box to	Indicate Nature of Not	ice, Report, or Other	Data	
NOTICE OF INTENTION TO:		SUBSEQUENT REF		
PERFORM REMEDIAL WORK  PLUG AND ABAND			ALTERING CASING	
TEMPORARILY ABANDON		<del>_</del>	PLUG AND	
PULL OR ALTER CASING MULTIPLE COMPLETION	CASING TEST A	AND	ABANDONMENT	
OTHER:	OTHER:			
12. Describe Proposed or Completed Operations (Clearly of starting any proposed work). SEE RULE 1103. For or recompilation.	state all pertinent details, as or Multiple Completions: At	nd give pertinent dates, in tach wellbore diagram of	cluding estimated date proposed completion	
**Procedure and Before and After Wellbore S	Schematics Attached**			
CONDITIONS OF APPROVAL All pits must be lined with plastic All shoe plugs, stub plugs & cement plugs above perfor				
be tagged All cement plugs pumped minimum 25 sxs & be minim				
be tagged				
All cement plugs pumped minimum 25 sxs & be mi	num 100 feet	pelief.	·	
All cement plugs pumped minimum 25 sxs & be mi	num 100 feet		ATE02/11/02	
All cement plugs pumped minimum 25 sxs & be mi	num 100 feet  he best of my knowledge and b	LATION/PRORATION D		
All cement plugs pumped minimum 25 sxs & be mi	num 100 feet  he best of my knowledge and b			

١...


-

## PLUG AND ABANDON WELL PROCEDURE SANTA FE #127

NOTE: Cement used is Class "C", density of 14.8 ppg, yield of 1.32 cubic feet per sack.


- 1. Notify NMOCD at (505) 393-6161, 24 hours prior to initiating plugging operations.
- 2. MIRU Plug & Abandon Package.
- 3. ND wellhead. NU PPCo. Class 1 shop tested BOP stack.
- 4. GIH w/ 2-3/8" WS open-ended and tag CIBP @ 3032'. Circulate 5-1/2" casing with 60 bbls 9.5 ppg mud-laden fluid.
- 5. Spot Plug No. 1, 15 sx. 3032 2888'. Plug will cover the CIBP & Yates.
- 6. POOH.
- 7. RU wireline unit. RIH & perforate 5 ½" csg at 2888'. POOH w/ WL.
- 8. TIH w/ AD-1Pkr & set at 2600'. Sqz. Plug No. 2, 35 sx., from 2888 2750'. Plug will cover the Salt Base. (WOC if pressure attained).
- 9. POOH w/ WS to 1500', set pkr. RIH & perforate 5 1/2" csg. at 1775'. POOH w/ WL.
- 10. Sqz. Plug No. 3, 25 sx from 1775 1675' (minimum interval). Plug will cover the Salt Top. (WOC if pressure attained).
- 11. Release packer & POOH to 360'. Set pkr.
- 12. RIH & perforate 5 1/2" csg. at 460'. POOH w/ WL.
- 13. Establish Circ on 5 ½ x 8 5/8" annulus. POOH w/ pkr. TIH w/ CICR & set at 360'.
- 14. Sqz. Plug #4 65 sx. 460' to surface. Unsting from CICR. Spot 45 sx 360' to surface. The plug will cover the surface csg. shoe & surface plug.
- 15. POOH. Top off. WOC. Tag cement and top off if necessary.
- 14. Cut off casing and wellhead 3' below GL and cap well. Install dry hole marker. Perform reclamation work.
- 15. Send forms and reports to: Phillips Regulatory
  4001 Penbrook
  Odessa, Texas 79762

## hillips Petroleum Company - Southwest Region October 16, 2001



File name: o:\everyone\wellfile\buckeye\santafe\sketch\Santa Fe #127.xls

## Phillips Petroleum Company - Southwest Region October 16, 2001



File name: o:\everyone\wellfile\buckeye\santafe\sketch\Santa Fe #127.xls