

Form 3160-5
(July 1989)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on re-
verse side)

30-025-24796
MM Roswell District
Modified Form No.
MD60-3160-4

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☒ OIL WELL ☒ GAS WELL ☐ OTHER		31. Area Code & Phone No. (505) 748-1288		5. LEASE DESIGNATION AND SERIAL NO. NM-077004	
2. NAME OF OPERATOR Mack Energy Corporation				6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P.O. Box 1359, Artesia, NM 88211-1359				7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit 0: 2310 FEL and 330 FSL				8. FARM OR LEASE NAME Collier Federal	
				9. WELL NO. #1	
				10. FIELD AND POOL, OR WILDCAT Tonto, Yates 7 Rivers, South	
				11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 19, T19S, R33E	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH Lea	
				13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to Plug and Abandon as follows:

Set CIBP @ 2900' w/35' cmt on top. Perf csg at 225' and circ cmt to surface. Install dry hole marker and clean location.

*NOTE: Gell plugs between cmt plugs.



18. I hereby certify that the foregoing is true and correct

SIGNED Crisa D. Carter

TITLE Production Clerk

DATE 11/20/92

(This space for Federal or State office use)

APPROVED BY David A. Glass


TITLE

DATE 12-28-92

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

MACK ENERGY CORPORATION
COLLIER FEDERAL #1
SEC 19 T19S R33E 330FSL 2310FEL



=====

WELL HISTORY

=====

PBTD: 3142'

TD: 3142'

SP Csg: 8 5/8" 24# @ 252' C/w 175sx cmt (CIRC 15sx Cmt)

LS Csg: 5 1/2" 15.5# @ 3072' C/w 500sx Cmt.

T SALT: 1318'

B SALT: 2730'

PERFS: 2982-94 (YATES)
OPEN HOLE 3072-3142

=====

COMPLETION REPORT

=====

7-18-74 Frac w/35000 gals gelled wtr and 350sx Sand.

=====

WELL REPORT

=====

11-18-92 PROPOSE TO PLUG AND ABANDON AS FOLLOWS: Set CIBP @ 2900' w/35' Cmt on top. Perf csg at 225' and Circ cmt to surface. Install dry hole marker and clean location.
* NOTE: Gell plugs between Cmt plugs.