

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Grande Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-24946
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. K-4513 and K-6237
7. Lease Name or Unit Agreement Name Midway State Com
8. Well No. 5
9. Pool name or Wildcat Lovington Devonian

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator GREENHILL PETROLEUM CORPORATION
3. Address of Operator 11490 WESTHEIMER, SUITE 200/HOUSTON, TEXAS 77077-6841	4. Well Location Unit Letter <u>K</u> : <u>2310</u> Feet From The <u>South</u> Line and <u>2310</u> Feet From The <u>West</u> Line Section <u>12</u> Township <u>17S</u> Range <u>36E</u> NMPM Lea County
10. Elevation (Show whether DF, RKE, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU PU & BOP. POOH w/production equipment.
2. RU wireline. TIH w/CIBP. Set CIBP @11,500'. TIH w/bailer, set 5sx cmt on plug.
3. TIH and perf @+ 8800' w/4 spf.
4. PU CET on tbg and TIH. Set CET @+ 8700'. SG2 perfs w/50sx cmt.
5. Cut 5 1/2" csg @ 4600' and POOH.
6. TIH w/tbg and spot cmt plug. from 4550' to 4450'. WOC. Tbg plug.
7. Per 8 5/8" csg. @+ 500'. TIH CET tool on tbg and set @ 400'.
8. Sqz 8 5/8" csg w/+ 100sx. Circ cmt to surface on 11 3/4" csg.
9. Set 10sx surface plug. Cut off wellhead 3 feet below ground level. Weld on dry hole marker.
10. Clean location.

I hereby certify that the information furnished is true and complete to the best of my knowledge and belief.

SIGNATURE David M. Tilley TITLE Engineer DATE 06-27-94

TYPE OR PRINT NAME David M. Tilley

TELEPHONE NO. (713) 589-8484

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

JUL 05 1994

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.

RECEIVED

JUL 01 1984

JCD HUBBS
OFFICE

RECEIVED

JUL 01 1984

JCD HUBBS
OFFICE