

DISTRIBUTION			
A F			
S.			
OFFICE			
OR			

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name Record	
9. Well No. 2	
10. Field and Pool, or Wildcat W. C.	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL ☐ GAS ☐ OTHER ☒ W. C.

2. Name of Operator
Dorchester Exploration

3. Address of Operator
Vaughn Building, Midland, Texas, 79701

4. Location of Well
E 1980 FEET FROM THE North LINE AND 660 FEET FROM West LINE, SECTION 26 TOWNSHIP 19 S RANGE 35 E NMPM.

15. Elevation (Show whether DF, RT, CR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
1. REMEDIAL WORK ☐	2. PLUG AND ABANDON ☒	3. REMEDIAL WORK ☐	4. ALTERING CASING ☐
5. PARTIALLY ABANDON ☐	6. CHANGE PLANS ☐	7. COMMENCE DRILLING OPNS. ☐	8. PLUG AND ABANDONMENT ☐
9. ALTER CASING ☐	10. OTHER ☐	11. CASING TEST AND CEMENT JOBS ☐	12. OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of completion.)

Cut 9 5/8 csg. at free point. Pull all of 9 5/8 csg out of hole. Run tubing 50 ft. inside the 9 5/8 csg. stub and pump 100 ft. plug using 70 sk of cement. Pull tubing to 560 ft. and pump a 100 ft. plug using 120 sk. of cement. Place a 10 sk. plug in top of 16 in. csg. and install dry hole marker.

IF SALT IS EXPOSED 100' Plug @ TOP of Salt

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed by H. A. Boudreau TITLE Agent date; 5/10/75

Signed by Les Clements TITLE Oil & Gas Insp. DATE 5/10/75

RECEIVED

MAY 13 1975

OIL CONSERVATION COMM.
HOBBS, N. M.