

**DISTRICT I**  
P.O. Box 1980, Hobbs, NM 88240  
**DISTRICT II**  
P.O. Box Drawer DD, Artesia, NM 88210  
**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	3002525085
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	858150
7. Lease Name or Unit Agreement Name	WEST VACUUM UNIT
8. Well No.	51
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

**SUNDRY NOTICES AND REPORTS ON WELL**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>I</u> : <u>1360</u> Feet From The <u>SOUTH</u> Line and <u>150</u> Feet From The <u>EAST</u> Line Section <u>33</u> Township <u>17S</u> Range <u>34E</u> NMPM <u>LEA</u> COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPERATION <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <u>Return to production</u> <input checked="" type="checkbox"/>	OTHER: <u></u> <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Move in and rig up pulling unit.
- TIH with 4 3/4" bit and drill out to 4760' (PBTD).
- TIH with 3 1/2" frac tbg and 5 1/2" Pkr.
- Set Pkr @ 4400'. Frac perfs 4515-4717'.
- Clean out to 4760' and return well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <u>M. Siamak Safargar</u>	TITLE <u>Prod. Engineer</u>	DATE <u>May 6, 97</u>
TYPE OR PRINT NAME <u>M. Siamak Safargar</u>	Telephone No. <u>397-0429</u>	

(This space for State Use) ORIGINAL SIGNED BY CHRIS WILLIAMS  
APPROVED BY DISTRICT I SUPERVISOR TITLE  DATE   
CONDITIONS OF APPROVAL, IF ANY:

1367 100-114-10  
MAY 1997  
Received  
Hobb  
000