

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
En , Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-25478
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1448
7. Lease Name or Unit Agreement Name STATE VACUUM UNIT
8. Well No. 21
9. Pool name or Wildcat VACUUM GRBG SA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT'
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> WIW
2. Name of Operator ARCO OIL AND GAS COMPANY
3. Address of Operator BOX 1710, HOBBS, NEW MEXICO 88240
4. Well Location Unit Letter <u>N</u> : <u>330</u> Feet From The <u>SOUTH</u> Line and <u>2310</u> Feet From The <u>WEST</u> Line Section <u>32</u> Township <u>17S</u> Range <u>34E</u> NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4081.1'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: TEMPORARILY ABANDON ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TA & HOLD WELL BORE FOR FUTURE USE

PERFS: 4764-4810'

1/2/91 RO. POH w/TBG AND SEAL ASSY. RIH w/PKR CATCHER TOOL. UNABLE TO RETRIEVE
PKR. POH w/CATCHER AND TBG. RIH w/BIT AND SCRAPER. SIDN.

1/3/91 RO. RIH w/CIBP. SET 1" ABOVE PKR. LAY DOWN 1 JT. CIRCULATE HOLE w/75
BBLs 8.6 BRINE w/WT675 PKR FLUID. POH w/TBG LAYING DOWN.

CIBP SET @ 4691.07'. PRESSURE TESTED FOR 15 MINS. @ 500#. MADE CHART.
WITNESSED BY RAY SMITH, NMOCD. CHART ATTACHED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James D. Cogburn TITLE Administrative Supervisor DATE 1/7/91
TYPE OR PRINT NAME James D. Cogburn TELEPHONE NO. 392-1600

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

This Approval of Temporary
Abandonment Expires 1-7-96

