## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES SCCCIVED	 
DISTRICUTION	
SANTA FE	
FILE	
U.\$.G.\$.	
LAND OFFICE	
OPERATOR	

## OIL CONSERVATION DIVISION P O BOX 2088

Form C-103

DISTRIBUTION	F. O. BOX	2008	Revised 10-1-7		
SANTA FE	SANTA FE, NEW	MEXICO 87501			
FILE			5a. Indicate Type of Lease		
U.\$.G.\$.			State X Foo		
LAND OFFICE			5. State Oil & Gas Lease No.		
OPERATOR			B <b>-</b> 1565		
SUNDRY	NOTICES AND REPORTS ON	WELLS	MILLIANI TO THE STATE OF THE ST		
COO NOT DENT BEU TON OC) USE "APPLICATION	NOTICES AND REPORTS ON SALS TO DELLE OR TO DEEPEN OR PLUG BA	CENTO A DIFFERENT RESERVOIR. H PROPOSALS.)			
OIL GAB WELL	7. Unit Agreement Name Central V cuum Unit				
2. Name of Operator			8. Farm or Lease Name		
TEXACO Inc.			Central Vacuum Unit		
3. Address of Operator			9. Well No.		
P O Boy 728 Hobbs	New Mexico 88240		56		
4. Location of Well	11011 11011200 002 0		10. Field and Pool, or Wildcat Vacuum Gray burg		
	North	LINE AND 2630 FEET FAO	San Andres		
UNIT LETTER	FEET FROM THE	LINE AND FEET PRO			
THE West LINE, SECTION	36 TOWNSHIP 17-3	RANGE 34-E NMPN			
mmmmm	Chamble Chamble	DE RT GR etc.	12. County		
15. Elevation (Show whether DF, RT, GR, etc.) 3999 (GR)			Lea		
16. Check Ap	propriate Box To Indicate N	ature of Notice, Report or O	ther Data		
NOTICE OF INT			IT REPORT OF:		
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING	PLUG AND ABANDON	REMEDIAL WORK  COMMENCE DRILLING OPNS.  CASING TEST AND CEMENT JQB  OTHER Add Perfs In	ALTERING CASING PLUG AND ABANDONMENT  San Andres		
OTHER	□				
17. Describe Proposed or Completed Oper work) SEE RULE 1103.	ations (Clearly state all pertinent deta	ails, and give pertinent dates, includir	ig estimated date of starting any processe.		
worny out none					

NOTICE OF INTENTION FILED TO REPAR CASING LEAK BUT REMEDIAL WORK RECOMMENDATION S/B FOR ADDL PERFS

RIGGED UP. INSTALL BOP. PULL TUBING AND PKR. 1.

PERFORATE 4 1/2" CSG W/2-JSPF @ 4341, 54, 76, 88, 4404, 49, 57, 4517, 82, 89, & 4608'. SET RBP @ 4640' AND PKR @ 4480'. ACIDIZE PERFS 4482-4615' 2.

3. W/4000 GALS 15% NEFE GEL ACID AND 1600# ROCK SALT.

RESET RBP @ 4500' AND PKR @ 4290,. ACIDIZE PERFS 4341-4461' W/4000 GALS 15% NEFE GEL ACID AND 1000# ROCK SALT.

5.	RAN 2 3/8" PLAST	IC COATE	D INJECTION	TUBING	W/PACK	ER AN	D SET
	@ 4243'. LOAD A	ANNULUS W	//INHIBITED	WATER.	RETUR	N WEI	LL TO
	WATER INJECTION,	9-26-84.	,				
	•						
y certify the	it the information above is true and	complete to the b	est of my knowledge s	nd belief.			
y certify the	at the information above is true and					_	
y certify the	it the information above is true and		District Opera		ager	DATE	10-18-84
	aliffe					<u> </u>	
	ddie W. Seay  & Gas Inspector					<u> </u>	<i>'0-18-84</i> CT 2 2 19