

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State ☒ Fee ☐
5. State Oil & Gas Lease No. D-155
7. Unit Agreement Name Central Vacuum Unit
8. Farm or Lease Name Central Vacuum Unit
9. Well No. 71
10. Field and Pool, or Wildcat Vacuum Grayburg San Andres
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER- Water Injection

2. Name of Operator
TEXACO Inc.

3. Address of Operator
P. O. Box 726 - Hobbs, New Mexico 88240

4. Location of Well
UNIT LETTER G 2630 FEET FROM THE North LINE AND 2623 FEET FROM
THE East LINE, SECTION 36 TOWNSHIP 17-S RANGE 24-E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)
4003' (GR)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPERARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER <u>Perforate & treat</u> ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TOTAL DEPTH 4800'
Plug Back Total Depth 4760'
8-5/8" OD 24# K-55 csg set @ 399'
4-1/2" OD 10.5# K-55 csg set @ 4000'

- Perforate 4-1/2" OD csg w/2 JSPF @ 4373', 83', 90', 4400', 19', 50', 60', 4531', 36', 48', 59', 60', 76', 4620', 31', 40', 50', 61', 71', 80', 88', 4703', & 4712'.
- Set RDP @ 4725' & pkr @ 4604'. Acidize perforations 4620-4712' w/3000 gals. 15% NE acid in 2 stages using 400# rock salt & Benzoic Acid Flakes between stages.
- Reset RDP @ 4604' & pkr @ 4511'. Acidize perfs 4531-4576' w/1800 gals 15% NE acid in 2 stages using 400# rock salt & Benzoic Acid Flakes between stages.
- Reset RDP @ 4511' & pkr @ 4325'. Acidize perfs 4373-4463' w/2100 gals. 15% NE acid in 2 stages using 200# rock salt & Benzoic Acid Flakes between stages. Pull pkr & RDP.
- Ran 2-3/8" plastic coated tubing w/pkr & set @ 4343'.
- Completed as shut-in water injection 2-22-78.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst. District Supt. DATE 2-24-78

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

100-2-81978

COMM.

COMM.

M. M.