

Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-10.
Revised March 25, 199

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO.
30-025-25808

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

857943

7. Lease Name or Unit Agreement Name

Central Vacuum Unit

8. Well No.

5

9. Pool name or Wildcat

Vacuum Grayburg SA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other Injector

2. Name of Operator

Texaco Exploration & Production, Inc.

3. Address of Operator

P. O. Box 3109, Midland, TX 79702

4. Well Location

Unit Letter D : 1310 feet from the North line and 1238 feet from the West line

Section 30

Township 17S Range 35E

NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. RIH w/Cicr, set @ 4200', Sqz (San Andres) w/75 Sx plug 4200'-4622'. WOC Test. Spot 20 Sx on Cicr.
2. Displace hole w/MLF, 9.5# brine w/25# gel P/BBL.
3. Spot 25 Sx plug 3800'-3600' (Queen)
4. Spot 25 Sx plug 2800'-2600' (Yates, B-Salt)
5. Spot 25 Sx plug 1400'-1200' (T-Salt) WOC Tag
6. Spot 25 Sx plug 500'-300' (8 5/8" shoe) WOC Tag
7. 10 Sx Surf, 10'-Surf. Install dry hole marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

James T. Corbitt

TITLE FACILITY ENGINEER

DATE 6-7-01

Type or print name

JAMES T. CORBITT

(This space for State use)

Telephone No. 915 688-443

APPROVED BY

Gary W. Wink

TITLE

ORIGINAL SIGNED BY

GARY WINK

FIELD REP. II

JUN 12 2001

DATE

PLUGGING & ABANDONMENT WORKSHEET (3 STRING CSNG)

OPERATOR TEXACO EXPLORATION & PRODUCTION
LEASENAME CENTRAL VACUUM UNIT

WELL # 5
SECT 30 TWN 17S RNG 35 E
FROM 1310 (N)SL 1238 E (W)L
TD: 4800 FORMATION @ TD SAN ANDRES
PBTD: FORMATION @ PBTD

85/8
@ 415
TOC SURF

	SIZE	SET @	TOC	TOC DETERMINED BY
SURFACE	85/8	415	SURF	Circ
INTMED 1				
INTMED 2				
PROD	4 1/2	4800	SURF	Circ
	SIZE	TOP	BOT	TOC DETERMINED BY
LINER 1				
LINER 2				
CUT & PULL @			TOP - BOTTOM	
INTMED 1			PERFS	4425 - 4622
INTMED 2			OPENHOLE	-
PROD				

* REQUIRED PLUGS DISTRICT I

RUSTLER (ANHYD)	
YATES	
QUEEN	
GRAYBURG	
SAN ANDRES	
CAPTAN REEF	
DELAWARE	
BELL CANYON	
CHERRY CANYON	
BRUSHY CANYON	
BONE SPRING	
GLORIETA	
BLINEBRY	
TUBB	
DRINKARD	
ABO	
WC	
PENN	
STRAWN	
ATOKA	
MORROW	
MISS	
DEVONIAN	

PLUG	TYPE PLUG	SACKS CMNT	DEPTH
EXAMPLES			
PLUG #1	OH	25 SXS	9850'
PLUG #2	SHOE	50 SXS	8700'-8800'
PLUG #3	CIBP/35'		5300'
PLUG #3	CIBP	25 SXS	5300'
PLUG #4	STUB	50 SXS	4600'-4700'
PLUG #6	RETNR SQZ	200 SXS	400
PLUG #7	SURF	10 SXS	0-10'
PLUG #1	CIRC	75 SX	4200-4622
PLUG #2	QUEEN	25 SX	3800-3600
PLUG #3	YATES	25 SX	2800-2600
PLUG #4	T-SALT	25 SX	1400-1200
PLUG #5	85/8 S	25 SX	500-300
PLUG #6	SURF	10 SX	10'-SURF
PLUG #7			
PLUG #8			
PLUG #9			
PLUG #10			
PLUG #			
PLUG #			

4 1/2
@ 4800
TOC SURF

TD 4800

