

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN THE MANNER
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	5. LEASE DESIGNATION AND SERIAL NO. NM-6869
2. NAME OF OPERATOR Union Oil Company of California	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 671 - Midland, Texas 79702	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below) At surface 660' FSL & 1980' FWL	8. FARM OR LEASE NAME Pipeline Deep Unit Federal
14. PERMIT NO.	9. WELL NO. 4
15. ELEVATIONS (Show whether DP, RT, GR, etc.) 3782' GR	10. FIELD AND POOL, OR WILDCAT North Quail Ridge Morrow Gas
	11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Sec. 6, T-19-S, R-34-E
	12. COUNTY OR PARISH Lea
	13. STATE NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRAC TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☐
Other:	☐		

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRAC TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
(Other) work on recompletion began	☒		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

- 10-15: LOADED 2-3/8 X 5-1/2 ANNULUS W/168 BFW. LOADED 2-3/8" TBG. W/50 BFW. PUMPED INTO MORROW PERFS 13065-13245 @1/2 BPM @3200 PSI W/7 BFW. RAN BAKER 1.87" BLANKING PLUG ON WIRE LINE & SET IN "ER" NIPPLE @12966'. PRESS TESTED PLUG TO 2500 PSI OK. MIRU DIAMOND WELL SERVICE. SWBD FL TO 10,000' & HAD NO FLUID ENTRY. LOADED 2-3/8" TBG W/40 BFW. ND TREE, NU BOP. REL FROM BAKER FH PKR @12,992' PU TO 12,974'. SDON. SPOT 25 SXS CLASS H CMT W/.2% WR-15 DOWN 2-3/8" TBG @12,992-12,765'. PU TO 10,800. SPOT 25 SXS CLASS H CMT W/.2% WR-15 FROM 10,800'-10,573'. PU TO 9820. REVERSED OUT. POOH. TIH W/4-3/4" BIT ON 2-3/8" TBG TO 10,580' & DID NOT TAG OUT. PU TO 9820'. REVERSED TBG CLEAN. SDON. FIH W/4-3/4" BIT TO TOC @10,742'. PU TO 9862'. SPOT 500 GAL 20% HCL NINE-40, XR-21, 1-17 ACID FROM 9862-9308'. PU TO 9799'. REVERSED OUT EXCESS ACID. DISPLACED HOLE W/212 BBLs 2% KCL PKR FLUID. POOH. RAN GR COL LOG FROM 10,668-8500'. RAN GUIBERSON UNI VI PKR W/4" TBG CONNED GUNS ON WL & SET PKR @9773'. SDON. R&L 309 JTS + 1 SUB (9756') 2-3/8" 4.7# N-80 EUE 8RD AB-MOD USED SMLS TBG TSTG INTERNALLY TO 5000#. LATCHED INTO PKR @9773' IN 12,000# COMPRESSION W/1.875 "F" NIPPLE @9715'. ND BOP. NU TREE. CROP FIRING BAR & PERF BONE SPRINGS THRU 5-1/2" CSG W/4" CSG GUN W/4 JSPF @9838-52' (56 TOTAL HOLES). OPEN WELL & HAD SLIGHT BLOW/8 MIN & DIED. SWI. SDON. LOADED 2-3/8" TBG W/15 BBLs 2% KCL WTR. PUMPED INTO PERFS 9838-52 W/4 BBLs @1.5 BPM @4500-4900 PSI. ISIP 4200 (15) 3950 PSI. TLTR 42 BBLs. SWBD 18 BW FOR 6 HRS. FL SUR-4800'. SDON. REL PKR, RIN TO 9855'. REV HOLE CLEAN. SPOT 500 GAL 20% HCL W/NE, FE & LST ACID FRM 9855-9306'. PU TO 9773' SET PKR. PUMP INTO PERFS 9838-52' @ .75-2 BPM @ 4000-4600 PSI W/500 GAL SPOT ACID. ISIP 4000 (15) 3150 PSI. TLTR 50 BBLs. SWBD 25 BW FOR 6 HRS. F-LVL SURF-5700' W/NO OIL SHOW. SDON. REL PKR & TOH, LD PERF GUN ASSY. RAN 5-1/2" GUIBERSON UNI-PKR ON 2-3/8" TBG TO 9895'. TSTD CSG & PKR & TBG TO 5000#, OK. PUH TO 9773'. SDON. ACIDIZE BONE SPRINGS PERFS 9838-52' W/2520 GAL 20% HCL W/940 & XR-21 ADDITIVES USED 75 1.3 SP GR BS. TREADED @ 2 BPM @ 4500-5000-4800-5200-5050 PSI. HAD SLIGHT BALL ACTION. ISIP 4300 (5) 3850 (10) 3700 (15) 3550 PSI. TLTR 99 BLW. SWBD 40 BW FOR 7 HRS. F-LVL SURF-9600'. NO OIL SHOW. SDON.

15. I hereby certify that the foregoing is true and correct

SIGNED Bobby Bryan
(This space for Federal or State office use)

TITLE Dir. Supt.

DATE 10-26-89

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

*See Instructions on Reverse Side

SJS

RECEIVED

NOV 13 1989

OCD
HOBBS OFFICE