Form 9-331 (May 1963)

UNITED STATES SUBMIT IN TRIPL TE

Form approved.
Budget Bureau No. 42-R1424.
LEASE DESIGNATION AND SERIAL NO.

DEPARTMENT OF THE INTERIOR verse a.de) GEOLOGICAL SURVEY			NM 6869	
SUNDRY NOTICES AND REPORTS ON WELLS			6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTICES A (Do not use this form for proposals to dril Use "APPLICATION FO	ND REPORIS ON It or to deepen or plug back R PERMIT—" for such propose	WELLS to a different reservoir. sals.)		
1.			7. UNIT AGREEMENT NAME Pipe Line Deep Unit	
General Exploration Company 3. ADDRESS OF OPERATOR 4219 Sigma Road, Dallas, Texas 75240			8. FABM OR LEASE NAME	
2. NAME OF OPERATOR General Exploration Company	.	四方门门自门		
3. ADDRESS OF OPERATOR	176	6 P 1 P P	9. WELL NO.	
4219 Sigma Road, Dallas, Texa			- 4 10. FIELD AND POOL, OR	3 WILDCAT
4. LOCATION OF WELL (Report location clearly and See also space 17 below.)	in accordance with any Sta	A MANUELLES	Undesignated	
4. LOCATION OF WELL (Report location clearly and in accordance with any Staff Exhibements.* See also space 17 below.) At surface U. S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO		11. SEC., T., R., M., OR S SURVEY OR AREA	LK. AND	
660' FSL and 1980' FWL	H	DBR2' War		
			Sec. 6, T-19	
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3,782 GL; 3800 KB.			Lea	New Mexico
			Oil Data	
16. Check Appropriat	te Box To Indicate Natu	ure of Notice, Report, or		
NOTICE OF INTENTION TO:		SUBSEC	QUENT REPORT OF:	
1891	LTER CASING	WATER SHUT-OFF FRACTURE TREATMENT	REPAIRING V	1
FRACTURE TREAT MULTIPLE SHOOT OF ACIDIZE ABANDON*	COMPLETE	SHOCTING OR ACIDIZING	ABANDONME	
REPAIR WELL CHANGE PI	LANS	(Other) Progress F	Report (Completi	ion) xxx
(Other)		Completion or Recom	ts of multiple completion pletion Report and Log to	: ш.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS / proposed work. If well is directionally drill nent to this work.) *	red, give Subsurface issues.			
3-03-79: Spotted 250 gallon	s, 15% MS acid (w	/t 10.5#/ga].)	from 13,100' - 1	12,850'.
Reverse circulated acid down tubing w	w/5 bbls. casing	j fluid and set pad ng fluid - ER 0 11	cker at 12,974 . 200 osia — ISDP	. Dispiaced - 3700 nsig
acid down tubing w Swabbed and well k	/o 1/2 DD15. Cd5+ icked off and sta	ng nuna. 15 e 40 inted unloading mud	d and acid water	r. Flowing
on a 3/4" choke wi	th 125 psig (stab	oilized). Est. vo	lume – 2 million	n MCF.
3-04-79. Acidized with 3000	gallons, $7 \frac{1}{2}$	MS acid and 28 BS	. Flushed w/48	barrels 10#
brine. ISCP - 480	O psig. Swabbed	and well kicked of	tr flowing acid	water with
WHP from 100 - 600 3-05-79: Shut down for Sund		1 3/4 CHORE W. JU	parg pressure.	
3-06-79. SITP - 4250 psig. Flowed all day to clean up.				
3_07_79. SITP - 4300 psid. Opened sleeve and pumped 14 bbls. fluid down hole. Pe				e. Perfor-
ated hole in tubing @ 12,935'. Circulated down casing and circulated off gas				
3-08-79: Ran in hole with tubing and seal assembly. Set "FH" hydraulic packer 166' above Model "D" packer at 12,992'. Model "D" packer set at 13,158'.				
2 00 70. Resumed running tu	hing and set "FH'	' packer at 12,292	' w/12,000# pum	p pressure.
Pressured up to 22	nn≠ to make sure	packer was set.	Set 5000# on Bai	ker Model TV
packer. Pressured 230 barrels treate	up back side to	2500 psi, U.K. U	isplaced mud fro le with hailer	om note with to clean up
230 barreis treate Ran a total of 412	inints 2 3/8" ti	bing and set at I	3,158'.	co crean ap.
Nam a cocar or riz	J011103 2 07 0 01		•	
18. I hereby certify that, the foresping is thus an	d correct			
Lattie tathe		lgent	RECORD AVE 3-9-	79 ——————————
SIGNED COMMAND		ACCEPTED FOR MAR 1 2	Mal	: 2 ==
(This space for Federal or Spate office use)		Honer	1979	
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE	MAR 1 X	SURVEY	
COSDITIONS OF SELECTAR AS AS A.		GEOLOG!	N MEXICO	
		HOBBS, NE	At 15	
	*See Instructions of	S. GEOLOGI HOBBS, NE		