······································			
N . OF COPIES RECEIVED		Form C-103	
DISTRIBUTION		Supersectes Old C-102 and C-103	
SANTAFE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65	
FILE			
1.5.G.S.		5a. Indicate Type of Lease	
LAND OFFICE		State X Fee	
OPERATOR]	5. State Oil & Gas Lease No. E-7824	
	DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO DAILL OF TO DEEPEN OR FLUG BACK TO A DIFFERENT RESERVOIR.	- inninninnin	
		7. Unit Agreement Name	
OIL X GAS WELL	OTHER-		
,	8. Farm or Lease Name		
Gulf Oil Corporatio	Lea "ED" State (NCT-A)		
Address of Cperator		9. Well No.	
P. O. Box 670, Hobb	DS, NM 88240	3	
4. Location of Well	1980 FEET FROM THE SOUTH LINE AND 660 FEET FR	10. Field and Pool, or Wildcat Quail Ridge	
	FEET FR	**	
West	CCTION 16 TOWNSHIP 19-S RANGE 34-E	AHHHHHHHHHHA	
TRE COC	CCTION TOWNSHIP RANGE NMP	*** {}}}})))))))))))))))))))))))))))))))	
AMAMMANINI,	15. Elevation (Show whether DF, RT, GR, etc.)	12. County	
	3761' GL	Lea	
	k Appropriate Box To Indicate Nature of Notice, Report or (
		NT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT X	
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB		
	OTHER		
OTHER			
17. Describe Froposed or Completed	d Operations (Clearly state all pertinent details, and give pertinent dates, include	na estimated date of stutting any managed	
uork) SEE RULE 1103.			
	-28-78. PU test tools. Trip in hole for DST #1		
choke - 15/16", sur	face choke - 3/8". Open tool 6:58 AM 11-29-78 f	or 30 minute IF. Very	
weak blow. ISI 60 m	ninutes, FF 60 minutes. Very weak blow throughouing & formation bluid. Temperature 137°, IHP 495	t. FSI 120 minutes, Re-	
covered 420' drilli	ing & formation bluid. Temperature 13/, IHP 495	7#, ISIP 3797#, FSIP	
	IF 137# - 192#, FF 201#-308#. Continue drilling.		
	Circulate & condition mud. Run logs. 12-10-78		
	acker failed. POH. Circulate & condition mud. GI		
9927-10,082 (155.)	. Open tool @ 8:30 PM 12-9-78 with weak blow, 15	minute IF, 60 minute ISI,	
120 minute FF, 240	minute FSI. IHP 5542#, FHP 5242#, ISFP 43#, ISI	8/#, FF 43#, FS1 2247#	
P&A from John Runyo	vals with Wireline Tester. Prepare to P&A. Verb on on 12-11-78 as follows. Plug #1 - 10,190-10,0	50' with 50 sacks Class C	
	Lug #2 - 8100-7960' with 50 sacks Class C, .5% CF		
	Class C neat. Plug #4 - 3200'-3090' with 100 s		
#5 - 1750-1650' with 50 sacks Class C neat. Job complete at 11:45 AM 12-11-78. All plugs displaced with 10# mud. LD DP & DC's. Remove BOP's. Cut off wellhead. Plug #6 - 0-50'			
		nead. Fing #0 - 0-50	
with to sacks class	C neat. Install dry hole marker.	nead. ring #0 - 0-50	

 te to the best of my knowledge and belief.	DATE 12-13-78
TITLE	DATE

CONDITIONS OF APPROVAL, IF ANY: