

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-26227
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. A-1320
7. Lease Name or Unit Agreement Name East Vacuum Gb/Sa Unit Tract 3202
8. Well No. 001
9. Pool name or Wildcat Vacuum Gb/SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3956' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator Phillips Petroleum Company
3. Address of Operator 4001 Penbrook St., Odessa, Texas 79762
4. Well Location Unit Letter <u>I</u> : <u>1330</u> Feet From The <u>South</u> Line and <u>South</u> Feet From The <u>1310</u> Line Section <u>32</u> Township <u>17-S</u> Range <u>35-E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3956' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: Cleaned out & acidized ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-14-92: R.U. DDU. NU BOP. COOH w/tbg + cable. COOH LD sub. GIH w/bit & scraper tag scale @ 4575'. Clean out to 4610' fell out of scale. COOH LD tools. GIH w/tbg. & pkr. Spot a 1 drum mixture of 405 + 2% KCl over perfs. Set pkr @ 3801 test back side ok. Pump remaining mix.

5-15-92: RU swab. Pump 1000 gal 15% NEFe HCl.

5-16-92: Release pkr. COOH w/tbg LD pkr. PU GIH w/sub equip & tbg. Set bottom of motor @ 4601'. ND BOP. Flange up wellhead start pumping. RD MO.

5-19-92: MIRU Charger. Pump 2 drums TH756 in 20 bbl. 2% KCl. Displace w/250 bbl 2% KCl w/5 gal. TC420 in first half.

5-21-92: Pump 24 hrs. 337 BOPD 412 BWPD. 156.6 MCF 25.1% CO2. 464.619 GOR.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Supv., Reg./Proration DATE 5-22-92
(915)
TYPE OR PRINT NAME L. M. Sanders TELEPHONE NO. 368-1488

(This space for State Use) APPROVED BY JERRY SEXTON
SUPERVISOR
APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

MAY 27 '92

RECEIVED

MAY 26 1992

OCD HOBBS OFFICE