## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

	T	
PISTRIBUTION		
SANTA FE		
FILE		
U.S.O.S.		
LAND OFFICE	$\mathbb{T}^{-}$	
02154700		

			OIL	- CONSERVA	HON DIVISION					
Γ	POITEBLETION			P. O. BO	× 2088			Form C-10		
	SANTA FE		s	ANTA FE. NEW	MEXICO 87501			Revised 1	19-1-78	
Г	FILE		•				· · · · · · · · · · · · · · · · · · ·	<del></del>		
1	U.S.O.S.			•		];	Sa. Indicate Typ	e of Lease	_	
-	LAND OFFICE	<del>                                     </del>				. 1	State X	F∙e	• 🔲	
<u></u>	OPERATOR.				•	Ī	5, State Oil & G	as Lease No.		
L		سسلبسا	j	7DT No. 20 0	25 26402	1	D 0063	-		
	-			API No. 30-0	25-26402		B-2863-	1		
		SUNDR	Y NOTICES A	ND REPORTS ON	WELLS	, l			////	
	ADD MOY USE THIS FORM	4 FOR PRO	POSALS SO DRILL (	PR TO DECPEN OR PLUG & " (FORM C-101) FOR SUC	ACR TA A DIFFFEEEUT BERFRURIE				/////	
							7. Unit Agreeme	ol Name	7777	
01L V										
~	in X weit	<u> </u>	OTHER-				East Vacuum Gb/SA Unit			
Non	ne of Operator						8. Farm or Leas		• .	
	Phillips Pet	rolew	m Company	•		.   .	East Vacuu		nit	
1 3 4	iress of Operator					<del></del>	Tr. 3374			
AGG	•		•			İ	3. WELL 140.			
	Rm. 401, 400	)l Penl	brook St, O	dessa, TX 7976	2		002	•		
Loc	ation of Well			•			10. Field and Pe	ool, or Wildcat		
	т.		2681	North	. 1092		1720111	Ch /Ch		
U	HIT LETTER	_ •	FEET P	North North	LINE AND 1092	EET FROM	Vacuum	GD/ SA	~~~	
					•	<b>N</b>			////	
_	wast		33	17-	S : RANGE 35-E				/////	
T	- 11000 - 11000 - 11000 - 11000 - 11000 - 11000 - 11000 - 11000 - 11000 - 11000 - 11000 - 11000 - 11000 - 11000		·•		- KANGE - 37 D	— K			/////	
$\overline{}$	mmm	m	WWW. 5		DE PT CP	<del></del>	77777777	<del>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</del>	444	
111		/////	111111 12. 5	evation (Show whether	Dr. KI. GK, etc.)	1	12. County		////	
		/////	/////	3949.4 GR		1	Lea .		/////	
			1 D	T- !- !!	Name - ( Name - D	0.1			~~~~	
	Č	uneck A	Appropriate B	ox to judicate v	lature of Notice, Repor	t or Othe	er Data			
	NOTICE	E OF IN	ITENTION TO	:	SUBSE	EQUENT	REPORT OF	:		
	•				·					
		•								
CAPO	ORM SCHEDIAL WORK		•	LUC AND ABANDON	REMEDIAL WORK	$\vdash$	ALTE	RING CASING		
E 14 P	DRARILY ASAMDON				COMMENCE DRILLING OPHS.		PLUG	AND ABAHDOHME	INT	
ULL	OR ALTER CASING		c	HANGE PLANS	CASING TEST AND CEMENT JOB					
					OTHER	_				
	Set CIBP abo	ve lo	ver injection	on interval []					<u> </u>	
07	HER DOC CIPI GDC	70 10.	11170001	Sir Tirect var A						
					<u> </u>					
		pleted Op	erations (Licarly	state all pertinent det	ails, and give pertinent dates,	including e	stimated date of	starting any p	roposed	
w	ork) SEE RULE 1103.									
	Do some and ad		+0 57	though lower int	ication intornal					
	Recommended	proced	ure to prug	back lower in	ection interval					
	MI & RU DDU.	Inst	all BOP. r	release & lower	pkr to check csq c	clearanc	ces. COOH	w/tbq		
MI & RU DDU. Install BOP. release & lower pkr to check csg clearar & pkr. GIH w/CIBP, set @ 4565'.										
	a par. Gin	w/ CIDI	, 500 6 450	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,						
							_			
	Rerun inject	ion eq	quipment: S	Set pkr @ 4540'	. Test CIBP w/1500	) psi.	Release pk	r & pull		
	to 4386'.							•		
			•	•						
		10 0		::	dame of Heighes 270		mless c wha	/35 0004	1	
		•			drum of Unichem 370		_	W/ T2,000#	ŧ	
	tension. Pr	essure	tst tbg-cs	sg annulus w/l5	500 psi. Return wel	ll to in	ijection.	•		
								•		
	•		•					•		
				•						
					•					
	•				_					
					•					
							_			
	BOP EQUIP:	Series	900, 3000	WP, double w/	set pipe rams, 1 se	et blind	d rams, mar	nually		
	operated.									
1 h	ereby certify that the inf	ormation	above is true and	complete to the best of	f my knowledge and belief.					
(	HIV.	1								
د \	41/M 16	/ <i>/</i>	<u> </u>				3 4	0.6		
46	1 XXXXX	V	V. J. Muelle	TITLE			DATE /-2	26-84		
_	1 fe de service	andra take	IDDDY CEVSAN			<del></del>		404	<u> </u>	
_	- /		JERRY SEXTON				Λli	C _ 3 198	<b>54</b>	
	DISTAIC	-: 15UP	ERVISOR				AU	G = 3 19	-	
104	CO AV			<u> </u>			-			