

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501Form C-103  
Revised 10-1-78

3a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
L-5316

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Sol West III	8. Farm or Lease Name Shearn West
3. Address of Operator P. O. Box 10151, El Paso, Texas 79992	9. Well No. 1
4. Location of Well UNIT LETTER <u>J</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>3</u> TOWNSHIP <u>17-S</u> RANGE <u>35-E</u> N.M.P.M.	10. Field and Pool, or Wildcat 6. Shoe Bar (Morrow)
15. Elevation (Show whether DF, RT, GR, etc.) 3,959.7' GL 3,975.7' KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

## SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Progress Report (Completion)</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 4-26-80: Swabbed an estimated 1/2 barrel distillate and 6 1/2 barrels water with fluid level swabbed down to 9500' from surface. Shut down.
- 4-27-80: Swabbed an estimated 1/2 barrel distillate and 15 barrels water with fluid level swabbed down to 9500' from surface. Shut down.
- 4-28-80: Loaded tubing with 3% KCL water. Pulled out of hole with Baker Lok-Set packer. Retrieved bridge plug. Shut down.
- 4-29-80: Released bridge plug and tripped out of hole. Layed down bridge plug.
- 4-30-80: Capped 35' of Class "H" cement on CIBP set at 12,804'. Ran and set a 5 1/2" O.D. CIBP at 12,280'. Capped CIBP with 35' of Class "H" cement. Ran and set a 5 1/2" O.D. CIBP at 10,060'. Capped CIBP with 35' of Class "H" cement. Shut down.
- 5-01-80: Tripped in hole with a total of 285 joints 2 3/8" tubing (strap 8892'). Set mechanical slips. Shut down.
- 5-02-80: Shut down.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Patty Robbins TITLE Agent DATE May 2, 1980APPROVED BY                      TITLE                      DATE                     

CONDITIONS OF APPROVAL, IF ANY: