

Submit 3 Copies  
to Appropriate -  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-26590
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name Mid-America State
2. Name of Operator Oryx Energy Company	8. Well No. 2
3. Address of Operator P.O. Box 26300, Oklahoma City, O.K. 73126-0300	9. Pool name or Wildcat East La Rica Morrow
4. Well Location Unit Letter <u>H</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>1</u> Township <u>19S</u> Range <u>34E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3949' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed

- 1.) MIRU. BLOW WELL DOWN. ND WH. NU BOP. RU WL. RIH W/5 1/2" CIBP & SET CIBP @ 10750'. DUMP 20' CMT ON CIBP. POH RD WL.
- 2.) TIH W/ 2 7/8" WS OE TO 10650' & DISPLACE HOLE W/9.5 #/GAL. MUD. POH W/2 7/8" TBG.
- 3.) WORK STRETCH ON 5 1/2" CSG. & CUT CSG. @ FREEPOINT. POH LD CSG. (NOTE: IF FREEPOINT IS SHALLOWER THAN 7900', CONTACT NMOGCC & REGION DRILLING DEPT. FOR MODIFIED PROCEDURE.)
- 4.) TIH W/2 7/8" WS OE TO 7900'. SPOT 50 SX CL'C' CMT PLUG FROM 7900' TO 7705'
- 5.) POH W/WS TO 4300'. SPOT 50 SX. CL.'C' CMT. PLUG FROM 4300' TO 4105'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jan Stevenson TITLE Proration Analyst DATE Sept. 18, 1991  
TYPE OR PRINT NAME Jan Stevenson (405) TELEPHONE NO. 752-7139

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: