State of New Mexico Form C-103 Submit 3 Copies to Appropriate
District Office Energy, Minerals and Natural Resources Department Revised 1-1-89 OIL CONSERVATION DIVISION WELL API NO. P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 30-025-26593 DISTRICTII Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Loase FEE X STATE DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 & State Oil & Gus Lease No. LG-3405 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lesse Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: WELL X WELL Apple MS 2. Name of Operator & Well No. Manzano Oil Corporation 505/623-1996 3. Address of Operator 9. Pool name or Wildcat P.O. Box 2107/Roswell, NM 88202-2107 Shoe Bar Mississippian 4. Well Location 660 North 1980 Unit Letter _ West . Feet From The Line and _ Feet From The Line Township 17 South Range 35 East Lea **NMPM** County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3936 GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 9/20/95 Unset pkr. POOH w/410 jts 2-7/8" N80 tbg. Set CIBP @ 12,919'. Put 10 sks Class H cement on top CIBP. Mudded up hole w/70 bbls. Spotted 25 9/21/95 sks Class C cement from 10,100' back to 9800'. Pulled to 8700'. Spotted 25 sks cement plug from 8700' back to 8400'. 9/22/95 Found free point @ 5990'. Make cut. Pulled 146 jts of 4-1/2" + pull stand cut-off. Set plug 5990' back to 5850'. Tag same @ 5860'. Set plug 5031' back to 4931'. 9/23/95 Tag same @ 4900'. Set 50 sk plug from 1600' back to 1500' and from 503' back to 403'. Set 40 sk surface plug. Rig down. Install dry hole marker.

Thereby certify that the information above is true and complete to the best of my knowledge and belief.

Signature Allicon Allicon Hernandez

TYPE OR PRINT NAME

Allicon Hernandez

THE Engineering Technician

DATE 11/09/95

THE Engineering Technician

DATE 11/09/95

THE PRESENTATIVE II

WAR 11 1996

CONDITIONS OF APPROVAL, IF ANY:

APPROVED BY

10