

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐ other Dual (Morrow-Bone Spring)
well well
2. NAME OF OPERATOR
Harvey E. Yates Company
3. ADDRESS OF OPERATOR
P. O. Box 1933, Roswell, New Mexico 88201
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660' FNL & 660' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH: Same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☒
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☒
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

- ☐
☒
☐
☐
☐
☒
☐
☐

RECEIVED
FEB 17 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

5. LEASE
NM-14789-a
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
Young Deep Unit
8. FARM OR LEASE NAME
9. WELL NO.
1
10. FIELD OR WILDCAT NAME
North Young Bone Spring - Morrow Gas
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 10, T-18S, R-32E
12. COUNTY OR PARISH 13. STATE
Lea NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3845.3' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Procedure

- 2/16/82 (1) MI & RU Well Service Unit. Record SITP & SICP.
(2) Load Morrow & Bone Spring Tubing & kill well.
(3) ND Dual tree, NU BOP w/2 1/16" & blind rams.
(4) Set pipe racks & catwalk.
- 2/17/82 (5) Release mod "K" DG packer. Pull & LD 2 1/16" OD CS, Hydril thd tubing. NOTE: Install protectors & handle tubing w/CARE.
- 2/19/82 (6) Release Lok-Set pkr, Pull & LD 2 1/16" OD psi-DWS thd N-80 tubing packers and Geo Vann tubing conveyed guns.
- 2/22/82 (7) RU wireline truck; GIH w/CIBP, set @ 12275' and Dump 35' cement on top CIBP. PBTD 12240'. RD wireline unit.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Peter W. Chester TITLE Engineer DATE 2/15/82

APPROVED BY CONDITIONS OF	ACCEPTED FOR RECORD PETER W. CHESTER FEB 19 1982 U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO	TITLE _____ DATE _____
------------------------------	---	------------------------

Young Morrow
NM (2/13/82)

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

- (8) ND BOP and Dual tubing spool. NU Single tbg
spool. NU BOP. Change 2 1/16" pipe to 2 3/8"
Pipe rams.
- (9) GIH w/Lok-Set pkr, SN and 2 3/8" EUE J-55 tbg.
Set pkr @ 8350'.
- (10) ND BOP. NU single tree. Swab test Bone Spring
Acidize w/2000 gals - 15% MSR 100 to improve
Flow rate.
- (12) 2/27/82 (12) Place well on production.

RECEIVED
FEB 21 1982
HOBBS CLARK

RECEIVED

FEB 21 1982