State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT

OIL CONSERVATION DIVISION

5. Indicate Type of Lease STATE X	PER
STATE A	FEE

P.O. Box 1980, Hobbs, NM 88240	Santa Fe. New Mexico 87504-2088		30-025-26649	
DISTRICT II P.O. Drawer DD, Artesia, NM \$8210			5. Indicate Type of Lesse STATE X FEE	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	0		6. State (Ni) & Gas Leese No. B-1576-3	
(DO NOT USE THIS FORM FOR F DIFFERENT RES (FORM	OTICES AND REPORTS ON PROPOSALS TO DRILL OR TO DE SERVOIR. USE "APPLICATION FO IC-101) FOR SUCH PROPOSALS.	EPEN OR PLUG BACK TO A REPERMIT!	7. Lease Name or Unit Agreement Name	
1. Type of Well: OL GAS WELL	one Wat	er Injection	E.Vac.Unit Tract 3229	
2 Name of Operator Phillips Petrol	eum Company		8. Well No. 007	
3. Address of Operator 4001 Penbrook S	treet, Odessa, Texa	as	9. Pool same or Wildcat East Vacuum	
4. Well Location Unit Letter K :	2600 Feet Prom The South	1 Line and 250	O Feet From The West Line	
Section 32	Township 17-S		NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3973' RKB - 3962' GL				
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF I	NTENTION TO:	SUB	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT				
PULL OR ALTER CASING CASING TEST AND CEMENT JOB				
OTHER: OTHER: Spot cement plug on bottom to shut-off X out of zone injection being lost thru a hole from 4557' - 4680', acid & return to injection				
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated state of starting any proposed				
2-12-92: GIH w/2-7			p 210 bbl fresh water to displace w/26 bbl water.	
COOH w/3	its. tbq. COOH w/8	3 jts. tbg.	-	
2-13-92: GIH w/tbg-tag top of cmt. @ 4648' - COOH - trip 7" scraper to 4200'. GIH w/7" pkr & tbg. Set pkr @ 4136'. Test csg/tbg annulus to 500# - OK. Pump 3000 gal CHIC acid, 4000# Rock Salt, 76 bbl Gelled Brine, and				
Pump 3000 38 bbl 2%		JU# ROCK Sait, /6	bbi Geiled Brine, and	
2-15-92: Unset pkr	- COOH LD workstr	ing. GIH w/7" Ba	ker LOC, Set pkr w/CO2 llars. Set wellhead. Set	
pkr 0 411	0' in 10 pts compre	ession. Test to	500# for 30 min. OK.	
	Rate - 729 BWPD @ 300			
I hereby cartify that the information above is	a true and complete to the best of any knowle		mountion 2-10-02	
SIGNATURE	1 - pices	Supv. Reg/P	UNIE	
TYPE OR PRINT HAME L. M.	Sanders		(015) 368-1488 TREATHONE NO.	
(This space for State Use) Pau	Signed by 1. Enuita			

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

FEB 2 5 1992

CD HOBBS ATTICE