

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-26650
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1576-3
7. Lease Name or Unit Agreement Name East Vacuum Gb/SA Unit Tract 3229
8. Well No. 009
9. Pool name or Wildcat Vacuum Gb/SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3960' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Phillips Petroleum Company
3. Address of Operator 4001 Penbrook St., Odessa, Texas 79762
4. Well Location Unit Letter <u>N</u> : <u>200</u> Feet From The <u>South</u> Line and <u>2500</u> Feet From The <u>West</u> Line Section <u>32</u> Township <u>17-S</u> Range <u>35-E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3960' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Acidized ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/16/92
MIRU DDU. NU BOP. COOH w/tbg & sub equip. MIRU Charger to pump 5000 gal 15% NEFE
HCl. SI RDMO Charger. RU swab. COOH. PU GIH w/sub equip and tbg. ND BOP.
Flange up wellhead. Start pumping. Test - 471 BOPD, 188 BWPD, 481.0 Mcf,
1043.859 GOR.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Supervisor Reg & Pro. DATE 6/16/92

TYPE OR PRINT NAME L. M. Sanders

TELEPHONE NO. 368-1488

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 17 1992

ON HOBBS DESK