

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-26651
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	A-1320
7. Lease Name or Unit Agreement Name	EAST VACUUM GB/SA UNIT TRACT 3229
8. Well No.	008
9. Pool name or Wildcat	VACUUM GB/SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER WATER INJECTION	
2. Name of Operator Phillips Petroleum Company	
3. Address of Operator 4001 Penbrook Street, Odessa, TX 79762	
4. Well Location Unit Letter N : 1300 Feet From The SOUTH Line and 2400 Feet From The WEST Line Section 32 Township 17-S Range 35-E NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3961' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: CLEANED OUT SAND ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/15/94 MIRU DDU. NU BOP. RELEASE PKR. AND COOH. PU GIH W/BIT, COLLARS AND TBG.  
11/16/94 TAG TOP OF SAND. START CIRC.  
11/17/94 CLEAN OUT FROM 4501'-4503'. CIRC. CLEAN.  
11/18/94 COOH COLLARS. GIH W/BIT AND TBG. CLEAN OUT FROM 4448'-4515'. CIRC. CLEAN.  
11/22/94 CLEANED OUT TO TD.  
11/23/94 GIH TESTING PKR AND INJ. TBG. SET PKR @4205. ND BOP. FLANGE UP WELLHEAD LOAD AND TEST CSG/PKR TO 500# FOR 30 MIN. OK. RD DDU.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE SUPERVISOR, REG. AFFAIRS DATE 12/05/94

TYPE OR PRINT NAME L. M. SANDERS TELEPHONE NO. 915/368-1488

(This space for State Use)

OFFICIAL COPY OF JAMES HEXTON  
DISTRICT I SUPERVISOR

DEC 07 1994

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 11 1964  
ALCO HOBBS  
OFFICE