

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-26654
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1334
7. Lease Name or Unit Agreement Name East Vacuum Gb/SA Unit Tract 3308
8. Well No. 005
9. Pool name or Wildcat Vacuum Gb/SA
10. Elevation (Show whether DP, RKB, RT, GR, etc.) 3948' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Phillips Petroleum Company

3. Address of Operator
4001 Penbrook Street, Odessa, TX 79761

4. Well Location
Unit Letter C : 175 Feet From The North Line and 2600 Feet From The West Line
Section 33 Township 17-S Range 35-E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Acidized <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-01-93 - MIRU DDU. COOH w/rods and pump. NU BOP. Unset TAC PU. GIH w/7" csg. scraper an tbg. to 2113'.

10-02-93 - Finish GIH w/scraper to 4636'. Tag @+/-4700'. Catch sample of salt and iron sulfide.

10-05-93 - Pump 6,000 gals acid.

10-06-93 - Swab.

10-07-93 - Pump scale squeeze.

10-08-93 - GIH w/tbg. and TAC. ND BOP. Flange up wellhead. GIH w/pump and rods.

10-13-93 - Pump 24 hrs: 160 BOPD; 285 BWPD; 197 Mcf.; 1194 GOR.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Supv. Regulatory Affairs DATE 10-18-93
TYPE OR PRINT NAME L. M. Sanders (915) TELEPHONE NO. 368-1488

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE OCT 22 1993

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

CD HOBBS
OFFICE