## STATE OF NEW MEXICO HERGY MO MINERALS DEPARTMENT

-0. 00 100183 00011940		
DISTRIBUTION		
SANTA PE		
FILE		
V.S.G.S.		ا
LAND OFFICE		ــــــــــــــــــــــــــــــــــــــ
OPERATOR	1	ł

ONDITIONS OF APPROVAL, IF ANYS

## OIL CONSERVATION DIVISION

Form C-103

DISTRIB		+			BOX				Revised 10-1-
BANTA PE	<u> </u>	+ 1 - 1	s	ANTA FE. N	MEM W	EXICO 87501	r	a. Indicate Typ	e of Lease
FILE							1	State X	F** 🗌
U.S.O.S.			1					5. Stole Otl 6 C	as Lease No.
LAND OFFIC		<del></del>	4						
OPERATOR			API NC	.30-025-266	55			B-1334	THITTINI
		SUMOR		AND DEDORT	S ON W	ELLS	<b></b> .		
(00 HOT U	8E THIS 75	SUNUK	OPOSALS TO DAILL	OR TO DEEPEN OR	PLUS BAC OR SUCH	PROPOSALS.)		7. Unit Agreem	ent Name
		April 2							ım Gb/SA Unit
•n 🕡	- 6A8		OTHER.					8. Fam or Lea	se Name
Name of Operate									um Gb/SA Unit
		- 1 C	'ompany					9. Well No. T	
Phillips Address of Open	s Petro	oream c	Ompany					004	1401 01
, Address U. Op-	- b-moole	c+ O	Odessa, TX	79762					Pool, or Wildcat
Location of We	.11							Vacuum G	
			200	T FROM THE NO	rth	LINE AND	FEET FROM	mm	IIIIIIII.
UMIT LETTER									
We	o t		33	*********	17-S	RANGE35-E	НМРМ.		
THE	<u> </u>	LINE, SECT						12. County	11111111111111111111111111111111111111
mm	rm	mm.	15.	Elevation (Show	whether	DF, RT, GR, etc.)			
				395	1'GR			Lea	
<u> </u>	77777	777777		Box To Indi	cate N	ature of Notice, Re	port or Ot	her Data	
: b.		Check	Vbbtohuste	TO:		รบ	BSEQUEN'	T REPORT	)F:
	NOT	TICE OF	INTENTION	10.					
		$\Box$		PLUE AND ASAM	ON []	REMEDIAL WORK	Ц		TERING CASING
	IAL WORK	님				COMMENCE DRILLING OPHI	•.   _	PL	US AND ABANDONMENT
TEMPORABILY AS		H		CHANGE PLANS		CASING TEST AND CEMENT	ן פסר ז	ouer perf	e acidized
FULL OR ALTER O	C A B 144					CARING TEST AND CEMENT OTHER Set CIBI	above	S. installe	ed beam pump
						trt'd IC	or scare	& Instarr	, ,
01HER						ails, and give persinent de	ere includin	e estimated date	e of starting any prof
" Describe Pr	roposed or	Completed	Operations (Cle	arly state all pert	inent del	tails, and give pertinent di	, the to-		_
mark) see	RULE I	03.	. 11 . J DOD	штн	Pon	2-3/8" tbg, set	@ 4610'.	Set 7" p	kr
7-17-86:	RU DD	U. Inst	lalled bor.	ecure un.	COOH	w/tbg & pkr.			
							hemical	mix @ 4580	•
7-18-86:	Tst'd	tog 11	AAO! saz'd	remaining	5½ bb	ls of chemical i	nto form	ation.	
- 10 0/	Set p	igod w/	2000 gals 1	5% NEFE HCI	w/2	drums Techniclea W	n 425 th	ru /" csg	peri
7-19-86:	ACLGI	LZEG W/ 4	2000 gdio - Swhd 4 h	rs, no oil,	45 B	W.			
7 00 06	C*011	-4500		•					/+ba
7-20-86:	Dmnd	2 drum	s 756 techr	nihib w/30 H	BFW, f	oll'd 240 Bbls f	lush wat	er. coon	w/ cog
7-21-86:	£ nk:	r. Set	2-3/8" tbs	g set @ 4593	31.				
7-22-86:	WTH	w/2" X	1½" pmp.						
7-23-86:	Pmnd	24 hrs	, no tst.						
7-24-86:	Pmpd	24 hrs	, 0 BO, 12	1 BW, .2 MC	FG				
7-25 thru	_					•			
7-26-86:	Pmpd	48 hrs	s, no test.						
7-27 thru	=				•				
12-14-86:	Pump	ing, no	test.						
12-15 thru			-100	- / MCEC	CO	22 8%			
12-29-86:	Pump	ing no	oil, 5128	BW, 4 MCFG,	2	22.0%.			
		complet							
	) 100	Compact				and an heartfales and he	lief.		
.8. I hereby	Auth the	the Inform	netion above is tr	rue and complete	to the be	st of my knowledge and be			
(4/	Wil								1-15-87
	Ms	47.	W. J.	. Mueller	TITLE F	Engr. Supvr. Resv	/Г•		
11500	4							*	Bank Cation
	SRIGUM	L SIGNED	BY JERRY SE	KTON					AN 1 8 196
۲ "	n	ISTRICT I	SUPERVISOR		FITLE				

The same of the sa