form D-1001-B

UNION OIL CO. OF CALIFORNIA REPAIR RECORD

SHEET B

PAGE NO.

LEASE Pipeline Deep Unit Fed. WELL NO. 5 FIELD North Quail Ridge

COMPLETION DATE: 6-16-81 APPROVED

DATE

E.I.D.

CONDITION OF THE HOLE BEFORE REPAIR

TOTAL DEPTH: 13570'

CASING RECORD: 13 3/8" 8RD 48# to 503'
9 5/8" 8RD 40 & 43.5# to 5295'
5 ½" 8RD 17# to 13620'

PERFORATIONS: 13,054' - 13,283'

TUBING DETAILS: 398 Jts (12,883') 2 7/8" 6.5# N-80

REASON FOR REPAIR: To Plug Morrow and make SWD Well in Yates Zone

CONDITION OF THE HOLE AFTER REPAIR

TOTAL DEPTH: 5175'

CHRISTMAS TREE TOP CONN.: 2 3/8"

CASING RECORD: 13 3/8" 8RD 48# to 503'

9 5/8" 8RD 40 & 43.5# to 5295' 5 ½" 8RD 17# 6900 to 13620'

PERFORATIONS: 3895' to 3940' - 2 SPF

3712-14, 26-28, 47-49, 65-67, 3799' to 3801' - 2 SPF

3990' to 4000' - 2 SPF 4177' to 4233' - 2 SPF

4445' to 4455' - 1 SPF

.... 33 1.33 1.511

TUBING DETAILS: 118 Jts. (3658') 2 3/8" IPC J-55 4.7#

TYPE: _Cameron

CASING HEAD: _13 3/8" Slip on x 12" 900 w/2-2" Outlets

CASING HANGER: _9 5/8" Slips

CASING SPOOL: _12" 900 x 10" - 5000 (National)

TUBING HEAD: __10" 5000 x 6"-5000 Cameron

TUBING HANGER: __HBA w/RFC

TUBING HEAD TOP: _6" - 5000 x 2 3/8" Tubing

MASTER VALVES: __Wheatly Ceramic Gate Valve - 3000#