STATE OF NEW MEXICO		
ENERGY AND MINERALS DEPARTMENT		
	ERVATION DIVISION	Form C-103
	0. BOX 2088	Revised 10-1-78
FILE SANIAFE	NEW MEXICO 87501	
U.3, G.8.		5a. Indicate Type-of Lease
LAND OFFICE		
OPERATOR		5. State Oll & Gas Lease No.
		<u>B-1839</u>
SUNDRY NOTICES AND REPOR	RTS ON WELLS OF PLUC BACK TO A DIFFERENT RESERVOIR. I FOR SUCH PROPOSALS.)	
01L . 6A3 .		7. Unil Agreement Name
WELL VELL OTHER.	······································	East Vacuum Gb/SA Unit
Name of Operator		8. Form or Lease Name
Phillips Petroleum Company		East Vacuum Gb/SA Unit
Address of Operator		9. Well No. Tract 2738 009
Room 401, 4001 Penbrook Street, Odessa,	Texas 79762	
Location of Well	<u>orth</u> Line and <u>50</u> Peet Pron	10. Field and Pool, or Wildcat Vacuum Gb/SA
		<u> AIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII</u>
THE WEST LINE, SECTION TOWNSHIP	<u>17-S</u> RANGE <u>35-E</u> NMPM	AIIIIIIIIIIIIIIIIIIIII
STATISTICS Show Show Show Show Show Show Show Sho	whether DF, RT, GR, etc.)	12. County
зули забот и забот и забот и страниции забот и как и страниции и страниции и страниции забот и как и страниции и	<u>3944.7'GR</u>	Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORE X PLUG AND ABAN		ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
FULL OR ALTER CABING CHANGE PLANS	CASING TEST AND CEMENT JOB	
	07 HER	L_
OTHER		
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1903.		
Recommended procedure to pressure test casing to determine if casing leak exists, evaluate condition of casing and repair:		
MI & RU DDU. Install BOP. Unseat packer. Tag PTD with bottom of tubing. Strap tubing		
out of hole. Clean out to PTD of 4710' in log from 4710' to 3700'. GIH with packer- Isolate perfs for pressure tests as follow	necessary. Run casing inspec- type RBP, RTTS-type packer, an	ction and caliber
Perforations RBP 3	Setting Depth	Packer Setting Depth
4642'-47', 4664'-68'	4685'	4600'
4533'-4546'	4590'	4515'
4474'-4497'	4515'	4458'
Establish injection rate in each set of pe pressures. Attempt to load tbg-csg annulu above injection tests.	erfs. Do not exceed 5000 psi. Is and observe communication du	Record rates and uring each of the
Reset RBP at 4420' and packer at 4320'. It tain 500 psi on tbg-csg annulus during thi	s step. Record rate and press	casing leak. Main- sure. <u>SEE REVERSE SIDE</u>
16. Thereby certify that the information above is true and complete to	the best of my knowledge and belief.	2-24-86
		voir
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR	TLE	MAR 3 - 1986
ALL TIMES OF NEWS LINE AND		

Further remedial work will be determined following analysis of the above results.

•

