

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

B-871

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name West Vacuum Unit
2. Name of Operator TEXACO Inc.	8. Farm or Lease Name West Vacuum Unit
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	9. Well No. 54
4. Location of Well UNIT LETTER L 2130 FEET FROM THE South LINE AND 810 FEET FROM THE West LINE, SECTION 33 TOWNSHIP 17-S RANGE 34-E N.M.P.M.	10. Field and Pool, or Wildcat Vacuum Grayburg San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 4047' (GR)	12. County Lea


16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER Addl. Perfs in San Andres <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Pull rods and tubing. Install BOP. Pull tubing.
2. Perf. 5½" Casing W/2-JSPF @ 4519', 22, 27, 37, 60, 79, 4612', 17, 20, 25, 27, 30, 34, 36, 42, and 4644'
3. Set pkr. @ 4452'. Acidize perfs W/6000 gals 15% NEFE Acid using 100# rock salt, 100# Benzoid acid flakes, 1 drum TL 90-202 and 75 Ball sealers.
4. Install pumping equipment. Test and place on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED  TITLE **Asst. Dist. Mgr.** DATE **11-28-83**

ORIGINAL SIGNED BY EDDIE SEAY

APPROVED BY **OIL & GAS INSPECTOR** TITLE _____ DATE **NOV 30 1983**

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
NOV 29 1983
TREASURY OFFICE