

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-1113-1

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection	7. Unit Agreement Name Central Vacuum Unit
2. Name of Operator TEXACO Inc.	8. Farm or Lease Name Central Vacuum Unit
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	9. Well No. 154
4. Location of Well UNIT LETTER D 45 FEET FROM THE North LINE AND 1185 FEET FROM THE West LINE, SECTION 30 TOWNSHIP 17-S RANGE 35-E NMPM.	10. Field and Pool, or Wildcat Vacuum Grayburg San Andres
11. Elevation (Show whether DF, RT, GR, etc.) 3987' (GR)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER Perforate & Treat <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TOTAL DEPTH 4800'
PLUG BACK TOTAL DEPTH 4739'
13 3/8" OD 48# K-55 Csg Set @ 350'
8 5/8" OD 24# K-55 Csg Set @ 1693'
4 1/2" OD 10.5# K-55 Csg Set @ 4800'

1. Perforated 4 1/2" Csg w/2-JSPF @ 4549', 50', 51', 58', 60', 62', 65', 76', 78', 80', 93', 98', 99', 4600', 18', 20', 21', & 4622'.
2. Set pkr. @ 4500'. Acidize perfs. 4549' - 4622' w/6000 gals. 15% NEFE Acid & 36 ball sealers.
3. Frac perfs 4549' - 4622' w/20,000 gals. gelled water & 19,000# Sand in 2-stages using 350# rock salt between stages.
4. Ran 2 3/8" plastic coated tubing w/pkr. & set @ 4487'.
5. Well completed Shut-In Water Injection Well, 6-8-81.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* TITLE **Asst. Dist. Mgr.** DATE **6-9-81**

APPROVED BY _____ TITLE _____ DATE **JUN 10 1981**

CONDITIONS OF APPROVAL, IF ANY: