

Scharb "8" #1

- DST #1 9622-9672' (Bone Spring) 15 min IF, Fair Blow, 1 hr ISI, 1 hr FF. GTS 25 min into FF max rate 5MCFGD, 3 hr FSI. Rev out 350' oil cut drl mud. IH 5102#, IF 162-213#, ISI 3036# FF 226-290# FSI 3639# FH 4961#. Sampler 150#. Rc. 25 cc oil cut mud & 100 cc oil, .9 CFG. Temp 142°F.
- DST #2 10,044-10,154' (Bone Spring) 15 min IF, Fair Blow, 1 hr ISI, 1 hr FF. Fair Blow. No gas to surf. 3 hr FSI. Rc 400' oil & 100' oil cut drl mud. IH 5397#, IF 92-132#, ISI-4195#, FF-126-202#, FSI 4214#, FH-5387#, Sampler 2250# Rc 10.96 CFG, 1350 cc oil & 150 cc gas cut mud. Temp. 141°.
- DST #3 10,464-10,536' (Bone Spring) 15 min if very weak blow. ISI 1 hr. 1/2 hr FF no blow. 1 1/2 hr FSI. POH. Ck plugged on TST tool. Sampler 210# rc 1000 cc drlg mud.
- DST #4 10,464-10,536' (Bone Spring) IF 15 min fair blow. 1 hr ISI. 1 hr FF Fair Blow. No gas to surf. 3 hr FSI. Rc 790' oil & gas cut mud. IH 5642#. IF 471-464#, ISI 4667#, FF 457-441#, FSI 4695#, FH 5634#. Sampler 2200#, rc 3.25 CFG, 100 cc oil, 1320 cc oil cut drlg mud. Temp 150°.
- DST #5 10,626-10,668' (Wolfcamp). 15 min IF Weak Blow. 1 hr ISI. 1 hr FF Weak blow through TST. 3 hr. FSI. Rc 30' drlg mud w/trace of oil. IH-5772#, IF-44-62#, ISI-2064#, FF-44-81#, FSI-3267#, FH-5772#. Sampler 250# rc 1.0 CFG, trace oil, 1800cc drlg mud. Temp 142°.