

Submit 3 Copies  
to Appropriate  
District Office.

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30 025 27394
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 18615
7. Lease Name or Unit Agreement Name Consolidated State
8. Well No. 2
9. Pool name or Wildcat Midway (Strawn)

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Barbara Fasken
3. Address of Operator 303 W. Wall, Suite 1900, Midland, TX 79701-5116	4. Well Location Unit Letter A : 990 Feet From The East Line and 990 Feet From The North Line Section 8 Township 17 Range 37 NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3779'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-23-95: RUPU, POW and LD rods & pump.  
1-24-95: POW with tubing. Set 5-1/2" CIBP at 10,650'.  
1-25-95: RIW to 10650' and displaced with 230 bbls. 9.5 ppg salt mud. Spotted 25 sx Class "C" cement @ 11,650'-10,385', 25 sx @ 8800'-8535', 25 sx @ 6300'-6035'.  
1-26-95: Nipple down wellhead, cut 5-1/2" casing at 4300', LD 1 jt. casing.  
1-27-95: POW and LD 50 jts. 5-1/2" casing.  
1-30-95: Finished laying down casing. RIW with tubing to 4535' and spotted 75 sx Class "C" cement at 4535'. WOC 2 hrs. RIW with wireline and tagged plug at 4165'. Spotted 40 sx @ 2000'-1852', 10 sx @ 60'. Rig down plugging equipment.  
2-10-95: Cut off casing and capped with steel plate and dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Davis Jr. TITLE Operations Superintendent DATE 3-1-95  
TYPE OR PRINT NAME Jimmy Davis, Jr. TELEPHONE NO. 915-687-1777

(This space for State Use)

APPROVED BY Johnny Robinson TITLE JO DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR 15 1933

JOJO HILL'S  
OFFICE