Submit 3 Copies to Appropriate District Office

State of New Mexico Minerals and Natural Resources Department Ener

Form C-103

Revised 1-1-89

P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVIS	WELL API NO.
P.O. Box 2088	
USTRICT II O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease STATE X FEE
STRICT III 00 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lesse No.
SUMPRY NOTICES AND REPORTS ON WITH S	B-1520
SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BAI	CK TO A 7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	The second of the region of th
Type of Well: OR. GAS WELL X OTHER	NORTH VACUUM ABO UNIT
Name of Operator Obil Producing TX & NM Inc.	8. Well No. 232
Address of Operator C/O Mobil Exploration 7 Producing US Inc. O. Box 633, Midland, TX 79702	
Well Location I hit Lenes A . 519 For B. North	. 560 East
Can Line and	Feet From The East Line
Section 25 Township 17S Range 34-E	NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, G KB-4026	K, etc.)
Check Appropriate Box to Indicate Nature of N	otice, Report, or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
FORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W	ORK ALTERING CASING
PORARILY ABANDON CHANGE PLANS COMMENCE	DRILLING OPNS. PLUG AND ABANDONMENT X
	T AND CEMENT JOB
	- AND CEMENT SOR []
ER:	1
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent a	lates, including estimated date of starting any proposed
Describe Proposed or Completed Operations (Clearly state all pertinens details, and give pertinent awark) SEE RULE 1103. -7-39 MIRU	
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent a work) SEE RULE 1103. -7-39 MIRU -8-39 RIH w/tbg & pkr. Set pkr @ 2100', establish in	nj. rate through collapsed csg.
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent a work) SEE RULE 1103. -7-39 MIRU -8-39 RIH w/tbg & pkr. Set pkr @ 2100', establish in Release prk, P00H w/tbg & pkr. RIH w/tbg & cr 2100'. Pump 50 sx Thixotropic cmt + 540 sx 39	nj. rate through collapsed csg. nt retainer. Set retainer @
Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent a work) SEE RULE 1103. -7-39 MIRU -8-39 RIH w/tbg & pkr. Set pkr @ 2100', establish in Release prk, P00H w/tbg & pkr. RIH w/tbg & cr 2100'. Pump 50 sx Thixotropic cmt + 540 sx 39 130 sx.	nj. rate through collapsed csg. nt retainer. Set retainer @ % low dense cmt. Stage in last
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent awark) SEE RULE 1103. -7-39 MIRU -8-39 RIH w/tbg & pkr. Set pkr @ 2100', establish in Release prk, P00H w/tbg & pkr. RIH w/tbg & cr 2100'. Pump 50 sx Thixotropic cmt + 540 sx 35 130 sx.	nj. rate through collapsed csg. nt retainer. Set retainer @ % low dense cmt. Stage in last
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent awork) SEE RULE 1103. -7-39 MIRU -8-39 RIH w/tbg & pkr. Set pkr @ 2100', establish in Release prk, P00H w/tbg & pkr. RIH w/tbg & cr 2100'. Pump 50 sx Thixotropic cmt + 540 sx 33 130 sx. -9-89 Set 100' (10sx CLC) cmt plug from 376-476. Se	nj. rate through collapsed csg. nt retainer. Set retainer @ % low dense cmt. Stage in last
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent awork) SEE RULE 1103. -7-39 MIRU -8-39 RIH w/tbg & pkr. Set pkr @ 2100', establish in Release prk, P00H w/tbg & pkr. RIH w/tbg & cr 2100'. Pump 50 sx Thixotropic cmt + 540 sx 33 130 sx. -9-89 Set 100' (10sx CLC) cmt plug from 376-476. Se	nj. rate through collapsed csg. nt retainer. Set retainer @ % low dense cmt. Stage in last
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent awork) SEE RULE 1103. -7-39 MIRU -8-39 RIH w/tbg & pkr. Set pkr @ 2100', establish in Release prk, P00H w/tbg & pkr. RIH w/tbg & cr 2100'. Pump 50 sx Thixotropic cmt + 540 sx 33 130 sx. -9-89 Set 100' (10sx CLC) cmt plug from 376-476. Se	nj. rate through collapsed csg. nt retainer. Set retainer @ % low dense cmt. Stage in last
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent awork) SEE RULE 1103. -7-39 MIRU -8-39 RIH w/tbg & pkr. Set pkr @ 2100', establish in Release prk, P00H w/tbg & pkr. RIH w/tbg & cr 2100'. Pump 50 sx Thixotropic cmt + 540 sx 33 130 sx. -9-89 Set 100' (10sx CLC) cmt plug from 376-476. Se	nj. rate through collapsed csg. nt retainer. Set retainer @ % low dense cmt. Stage in last
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent a work) SEE RULE 1103. -7-39 MIRU -8-39 RIH w/tbg & pkr. Set pkr @ 2100', establish in Release prk, P00H w/tbg & pkr. RIH w/tbg & cr 2100'. Pump 50 sx Thixotropic cmt + 540 sx 33 130 sx. -9-89 Set 100' (10sx CLC) cmt plug from 376-476. Se	nj. rate through collapsed csg. nt retainer. Set retainer @ % low dense cmt. Stage in last
Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent a work) SEE RULE 1103. -7-39 MIRU -8-39 RIH w/tbg & pkr. Set pkr @ 2100', establish in Release prk, P00H w/tbg & pkr. RIH w/tbg & cr. 2100'. Pump 50 sx Thixotropic cmt + 540 sx 39 130 sx. -9-89 Set 100' (10sx CLC) cmt plug from 376-476. Semarker. RD & Rel. Pool WS	nj. rate through collapsed csg. it retainer. Set retainer @ % low dense cmt. Stage in last et 60 surf. plug. Weld P & A
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent a work) SEE RULE 1103. -7-39 MIRU -8-39 RIH w/tbg & pkr. Set pkr @ 2100', establish in Release prk, P00H w/tbg & pkr. RIH w/tbg & cr. 2100'. Pump 50 sx Thixotropic cmt + 540 sx 39 130 sx. -9-89 Set 100' (10sx CLC) cmt plug from 376-476. Semarker. RD & Rel. Pool WS	nj. rate through collapsed csg. it retainer. Set retainer @ % low dense cmt. Stage in last et 60 surf. plug. Weld P & A
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent awork) SEE RULE 1103. -7-39 MIRU -8-39 RIH w/tbg & pkr. Set pkr @ 2100', establish in Release prk, P00H w/tbg & pkr. RIH w/tbg & cr 2100'. Pump 50 sx Thixotropic cmt + 540 sx 33 130 sx. -9-89 Set 100' (10sx CLC) cmt plug from 376-476. Se marker. RD & Rel. Pool WS	rate through collapsed csg. It retainer. Set retainer @ Collapsed csg. It retainer @ Colla
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent awork) SEE RULE 1103. -7-39 MIRU -8-39 RIH w/tbg & pkr. Set pkr @ 2100', establish in Release prk, P00H w/tbg & pkr. RIH w/tbg & cr 2100'. Pump 50 sx Thixotropic cmt + 540 sx 33 130 sx. -9-89 Set 100' (10sx CLC) cmt plug from 376-476. Se marker. RD & Rel. Pool WS	nj. rate through collapsed csg. it retainer. Set retainer @ 6 low dense cmt. Stage in last et 60 surf. plug. Weld P & A GRATION & PRODUCING US INC. HAGSIL PROJECTED A NAME NO. DATE 2-21-89
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent of work) SEE RULE 1103. -7-89 MIRU -8-89 RIH w/tbg & pkr. Set pkr @ 2100', establish in Release prk, P00H w/tbg & pkr. RIH w/tbg & cr. 2100'. Pump 50 sx Thixotropic cmt + 540 sx 39 130 sx. -9-89 Set 100' (10sx CLC) cmt plug from 376-476. Semarker. RD & Rel. Pool WS	rate through collapsed csg. It retainer. Set retainer @ Collapsed csg. It retainer @ Colla