Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Santa Fe, New Mexico 87504-2088

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

P.O. Drawer DD, Artesia, NM 88210

OIL CONSERVATION DIVISION P.O. Box 2088

WELL API NO. 30-025-27606

5. Indicate Type of Lease

STATE FEE

DISTRICT III
1000 Rio Brazos Rd., Aziec, NM 87410 6. State Oil & Gas Lease No. A-1320 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: East Vacuum Gb/SA Unit WELL ones W.I. per PMX #122 Tract 3202 2 Name of Operator 8. Well No. Phillips Petroleum Company 010 3. Address of Operator 9. Pool name or Wildcut 4001 Penbrook Street. <u>Odessa</u>, TX 79762 Vacuum Gb/SA Well Location A : 1200 Feet From The __ Line and 50 Peet From The North East Township hip 17-S Range 35-E 10. Elevation (Show whether DF, RKB, RT, GR, etc.) Section NMPM Lea County 3953' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK **ALTERING CASING** TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT

OTHER:			OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.				
03-31-91:	MTRU DDU.	ND wellhead: NU BOP		

CASING TEST AND CEMENT JOB

- Clean out from +/-4490' to +/-4742'. 04-01-91:
- 04-02-91: MIRU HLS and run casing inspection log. GIH w/RBP, packer & tubing. Set RBP @ 4728'; set packer @ 4570'.
- 04-03-91: MIRU Charger to pump 500 gals CHIC acid. ISIP 300#; Max.Press. 750#.
- 04-04-91: Set RBP @ 4570'. Pull packer above perfs & SD.
- 04-05 to Set RBP @ 4670'; dump 4 sx sand on top. Pump 3000 gals CHIC acid,
- 3000# rock salt in 56 bbls gelled brine and 32 bbls 2% KCL flush. 04-06-91: ISIP: 250#; Max.Press. 1050#. Swab.
- GIH w/CO2 pkr, IPC inj.tbg (changing out collars to Texas Arai using 04-08 to
- seal lube). Test to 5000#. MIRU tbg. tester; test to 500#. ND BOP. 04-09-91: Flange up wellhead.
- MIRU. Load & test csg/tbg annulus for NMOCD to 500# for 30 mins; ok. 04-10 to
- Hook up & start injection. Inj. @ 564 bbls/d @ 1050#. Job complete. 04-13-91:

I hereby certify that the information above its joys and complete to the best of my knowledge and belief. ms Reg. & Proration Supv. DATE 04-23-91 SIGNATURE TYPE OR PRINT NAME Sanders TELEPHONE NO. 368-1387

- TITLE -

for Same Uni) 이런데데데 이 디디에게 이 디디에게 되었다고 나를 보기하다. CONTROL CONTROL OF

11

PULL OR ALTER CASING