STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

we. or carite accrives	
DISTRIBUTION	
SANTA PE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE, NEW MEXICO 87501

Form C-103 Revised 10-1-78

. U.S.O.S.		State XX Fee
LAND OFFICE		State XX Fee 5. State Oil & Gas Lease No.
OPERATOR	·	LG-3173
	SUNDRY NOTICES AND REPORTS ON WELLS	
(00 NOT USE 1	THIS FORM FOR PROPOSALS TO PAILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)	7, Unit Agreement Name
1. 01L	WELL X OTHER-	7. Ont Agreement None
2. Name of Operator	WILL C. J. OTHER-	8. Farm or Lease Name
Unic	on Oil Company of California	Maduro Unit
3. Address of Operator		9. Well No.
	D. Box 671 Midland, Texas 79702	3
4. Location of Well	1000	10. Field and Pool, or Wildcat
UNIT LETTER	F 1880 FEET FROM THE North LINE AND 1980 FEET FRO	Undesignated Morrow
West	LINE, SECTION 33 TOWNSHIP 19-S RANGE 33-E NMPH	
THE WEST	LINE, SECTION TOWNSHIP RANGE	
mmm	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3,539' GR	Lea
10.	Check Appropriate Box To Indicate Nature of Notice, Report of O	ther Data
		T REPORT OF:
PERFURIA REMEDIAL W	ORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		PLUG AND ABANDONMENT
PULL OR ALTER CABING	CHANGE PLANS CASING TEST AND CEMENT JOB OTHER Perf., treat, t	est and attempt
OTHER	completion in Lower 8	Middle Morrow and
	Bone Springs	
	d or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includir	ng estimated date of starting any proposed
WU/X/ SEE HULE	1103.	
wurk) SEE RULE		
•	Perf Lower Morrow 13,484'-13,493' w/4 SPF, GTS in 30 min v	w/2'-4' flare,
	Perf Lower Morrow 13,484'-13,493' w/4 SPF, GTS in 30 min water to surface in 33 min. On 1" choke flwd water & gas	w/2'-4' flare, w/no tbg press.
3- 3-82	Perf Lower Morrow 13,484'-13,493' w/4 SPF, GTS in 30 min water to surface in 33 min. On 1" choke flwd water & gas Rec 120 BW in 6 hrs. On final test flwd to pit 10-1/2 hrs choke. Set CIBP @ 13,452' in 10' tbg sub.	w/2'-4' flare, w/no tbg press. s 210 BW on 1"
3- 3-82	Perf Lower Morrow 13,484'-13,493' w/4 SPF, GTS in 30 min water to surface in 33 min. On 1" choke flwd water & gas Rec 120 BW in 6 hrs. On final test flwd to pit 10-1/2 hrs choke. Set CIBP @ 13,452' in 10' tbg sub. Perf Middle Morrow 13,140', 13,143', 13,145'-13,149', 13,145'	w/2'-4' flare, w/no tbg press. s 210 BW on 1"
3- 3-82	Perf Lower Morrow 13,484'-13,493' w/4 SPF, GTS in 30 min water to surface in 33 min. On 1" choke flwd water & gas Rec 120 BW in 6 hrs. On final test flwd to pit 10-1/2 hrs choke. Set CIBP @ 13,452' in 10' tbg sub. Perf Middle Morrow 13,140', 13,143', 13,145'-13,149', 13,113,204'-13,208', 13,217'-13,220' & 13,368'-13,369' w/4" cs	w/2'-4' flare, w/no tbg press. s 210 BW on 1" 155'-13,171', sg gun @ 4 SPF.
3- 3-82	Perf Lower Morrow 13,484'-13,493' w/4 SPF, GTS in 30 min water to surface in 33 min. On 1" choke flwd water & gas Rec 120 BW in 6 hrs. On final test flwd to pit 10-1/2 hrs choke. Set CIBP @ 13,452' in 10' tbg sub. Perf Middle Morrow 13,140', 13,143', 13,145'-13,149', 13,143', 13,204'-13,208', 13,217'-13,220' & 13,368'-13,369' w/4" cs Tested w/no reaction after perf. Set 5-1/2" CIBP @ 13,073	w/2'-4' flare, w/no tbg press. s 210 BW on 1" 155'-13,171', sg gun @ 4 SPF.
3- 3-82	Perf Lower Morrow 13,484'-13,493' w/4 SPF, GTS in 30 min water to surface in 33 min. On 1" choke flwd water & gas Rec 120 BW in 6 hrs. On final test flwd to pit 10-1/2 hrs choke. Set CIBP @ 13,452' in 10' tbg sub. Perf Middle Morrow 13,140', 13,143', 13,145'-13,149', 13,13,204'-13,208', 13,217'-13,220' & 13,368'-13,369' w/4" cs Tested w/no reaction after perf. Set 5-1/2" CIBP @ 13,073 on top to 13,038'.	w/2'-4' flare, w/no tbg press. 210 BW on 1" 155'-13,171', sg gun @ 4 SPF. 3' w/35' cement
3- 3-82	Perf Lower Morrow 13,484'-13,493' w/4 SPF, GTS in 30 min water to surface in 33 min. On 1" choke flwd water & gas Rec 120 BW in 6 hrs. On final test flwd to pit 10-1/2 hrs choke. Set CIBP @ 13,452' in 10' tbg sub. Perf Middle Morrow 13,140', 13,143', 13,145'-13,149', 13,113,204'-13,208', 13,217'-13,220' & 13,368'-13,369' w/4" cs Tested w/no reaction after perf. Set 5-1/2" CIBP @ 13,073 on top to 13,038'. Perf Bone Springs @ 8,168'-8,173' w/4" csg gun 4 SPF & acc	w/2'-4' flare, w/no tbg press. s 210 BW on 1" 155'-13,171', sg gun @ 4 SPF. 3' w/35' cement idized w/5,000
3- 3-82	Perf Lower Morrow 13,484'-13,493' w/4 SPF, GTS in 30 min water to surface in 33 min. On 1" choke flwd water & gas Rec 120 BW in 6 hrs. On final test flwd to pit 10-1/2 hrs choke. Set CIBP @ 13,452' in 10' tbg sub. Perf Middle Morrow 13,140', 13,143', 13,145'-13,149', 13,113,204'-13,208', 13,217'-13,220' & 13,368'-13,369' w/4" cs Tested w/no reaction after perf. Set 5-1/2" CIBP @ 13,073 on top to 13,038'. Perf Bone Springs @ 8,168'-8,173' w/4" csg gun 4 SPF & acc gals 15% HCL acid. No reaction after testing. Released 1	w/2'-4' flare, w/no tbg press. s 210 BW on 1" 155'-13,171', sg gun @ 4 SPF. 3' w/35' cement idized w/5,000 packer, POOH
3- 3-82	Perf Lower Morrow 13,484'-13,493' w/4 SPF, GTS in 30 min water to surface in 33 min. On 1" choke flwd water & gas Rec 120 BW in 6 hrs. On final test flwd to pit 10-1/2 hrs choke. Set CIBP @ 13,452' in 10' tbg sub. Perf Middle Morrow 13,140', 13,143', 13,145'-13,149', 13,113,204'-13,208', 13,217'-13,220' & 13,368'-13,369' w/4" cs Tested w/no reaction after perf. Set 5-1/2" CIBP @ 13,073 on top to 13,038'. Perf Bone Springs @ 8,168'-8,173' w/4" csg gun 4 SPF & acc	w/2'-4' flare, w/no tbg press. s 210 BW on 1" 155'-13,171', sg gun @ 4 SPF. 3' w/35' cement idized w/5,000 packer, POOH
3- 3-82	Perf Lower Morrow 13,484'-13,493' w/4 SPF, GTS in 30 min water to surface in 33 min. On 1" choke flwd water & gas Rec 120 BW in 6 hrs. On final test flwd to pit 10-1/2 hrs choke. Set CIBP @ 13,452' in 10' tbg sub. Perf Middle Morrow 13,140', 13,143', 13,145'-13,149', 13,113,204'-13,208', 13,217'-13,220' & 13,368'-13,369' w/4" cs Tested w/no reaction after perf. Set 5-1/2" CIBP @ 13,073 on top to 13,038'. Perf Bone Springs @ 8,168'-8,173' w/4" csg gun 4 SPF & acc gals 15% HCL acid. No reaction after testing. Released 1 w/tbg. Set CIBP on wire line @ 8,060' dumped 35' cement of the control of the co	w/2'-4' flare, w/no tbg press. s 210 BW on 1" 155'-13,171', sg gun @ 4 SPF. 3' w/35' cement idized w/5,000 packer, POOH
3- 3-82	Perf Lower Morrow 13,484'-13,493' w/4 SPF, GTS in 30 min water to surface in 33 min. On 1" choke flwd water & gas Rec 120 BW in 6 hrs. On final test flwd to pit 10-1/2 hrs choke. Set CIBP @ 13,452' in 10' tbg sub. Perf Middle Morrow 13,140', 13,143', 13,145'-13,149', 13,113,204'-13,208', 13,217'-13,220' & 13,368'-13,369' w/4" cs Tested w/no reaction after perf. Set 5-1/2" CIBP @ 13,073 on top to 13,038'. Perf Bone Springs @ 8,168'-8,173' w/4" csg gun 4 SPF & acc gals 15% HCL acid. No reaction after testing. Released 1 w/tbg. Set CIBP on wire line @ 8,060' dumped 35' cement of the control of the co	w/2'-4' flare, w/no tbg press. s 210 BW on 1" 155'-13,171', sg gun @ 4 SPF. 3' w/35' cement idized w/5,000 packer, POOH
3- 3-82	Perf Lower Morrow 13,484'-13,493' w/4 SPF, GTS in 30 min water to surface in 33 min. On 1" choke flwd water & gas Rec 120 BW in 6 hrs. On final test flwd to pit 10-1/2 hrs choke. Set CIBP @ 13,452' in 10' tbg sub. Perf Middle Morrow 13,140', 13,143', 13,145'-13,149', 13,113,204'-13,208', 13,217'-13,220' & 13,368'-13,369' w/4" cs Tested w/no reaction after perf. Set 5-1/2" CIBP @ 13,073 on top to 13,038'. Perf Bone Springs @ 8,168'-8,173' w/4" csg gun 4 SPF & acc gals 15% HCL acid. No reaction after testing. Released 1 w/tbg. Set CIBP on wire line @ 8,060' dumped 35' cement of the control of the co	w/2'-4' flare, w/no tbg press. s 210 BW on 1" 155'-13,171', sg gun @ 4 SPF. 3' w/35' cement idized w/5,000 packer, POOH
3- 3-82	Perf Lower Morrow 13,484'-13,493' w/4 SPF, GTS in 30 min water to surface in 33 min. On 1" choke flwd water & gas Rec 120 BW in 6 hrs. On final test flwd to pit 10-1/2 hrs choke. Set CIBP @ 13,452' in 10' tbg sub. Perf Middle Morrow 13,140', 13,143', 13,145'-13,149', 13,113,204'-13,208', 13,217'-13,220' & 13,368'-13,369' w/4" cs Tested w/no reaction after perf. Set 5-1/2" CIBP @ 13,073 on top to 13,038'. Perf Bone Springs @ 8,168'-8,173' w/4" csg gun 4 SPF & acc gals 15% HCL acid. No reaction after testing. Released 1 w/tbg. Set CIBP on wire line @ 8,060' dumped 35' cement of the control of the co	w/2'-4' flare, w/no tbg press. s 210 BW on 1" 155'-13,171', sg gun @ 4 SPF. 3' w/35' cement idized w/5,000 packer, POOH
3- 3-82	Perf Lower Morrow 13,484'-13,493' w/4 SPF, GTS in 30 min water to surface in 33 min. On 1" choke flwd water & gas Rec 120 BW in 6 hrs. On final test flwd to pit 10-1/2 hrs choke. Set CIBP @ 13,452' in 10' tbg sub. Perf Middle Morrow 13,140', 13,143', 13,145'-13,149', 13,113,204'-13,208', 13,217'-13,220' & 13,368'-13,369' w/4" cs Tested w/no reaction after perf. Set 5-1/2" CIBP @ 13,073 on top to 13,038'. Perf Bone Springs @ 8,168'-8,173' w/4" csg gun 4 SPF & acc gals 15% HCL acid. No reaction after testing. Released 1 w/tbg. Set CIBP on wire line @ 8,060' dumped 35' cement of the control of the co	w/2'-4' flare, w/no tbg press. s 210 BW on 1" 155'-13,171', sg gun @ 4 SPF. 3' w/35' cement idized w/5,000 packer, POOH
3- 3-82	Perf Lower Morrow 13,484'-13,493' w/4 SPF, GTS in 30 min water to surface in 33 min. On 1" choke flwd water & gas Rec 120 BW in 6 hrs. On final test flwd to pit 10-1/2 hrs choke. Set CIBP @ 13,452' in 10' tbg sub. Perf Middle Morrow 13,140', 13,143', 13,145'-13,149', 13,113,204'-13,208', 13,217'-13,220' & 13,368'-13,369' w/4" cs Tested w/no reaction after perf. Set 5-1/2" CIBP @ 13,073 on top to 13,038'. Perf Bone Springs @ 8,168'-8,173' w/4" csg gun 4 SPF & acc gals 15% HCL acid. No reaction after testing. Released 1 w/tbg. Set CIBP on wire line @ 8,060' dumped 35' cement of the control of the co	w/2'-4' flare, w/no tbg press. s 210 BW on 1" 155'-13,171', sg gun @ 4 SPF. 3' w/35' cement idized w/5,000 packer, POOH
3- 3-82 3-11-82 3-17-82	Perf Lower Morrow 13,484'-13,493' w/4 SPF, GTS in 30 min water to surface in 33 min. On 1" choke flwd water & gas Rec 120 BW in 6 hrs. On final test flwd to pit 10-1/2 hrs choke. Set CIBP @ 13,452' in 10' tbg sub. Perf Middle Morrow 13,140', 13,143', 13,145'-13,149', 13,113,204'-13,208', 13,217'-13,220' & 13,368'-13,369' w/4" cs Tested w/no reaction after perf. Set 5-1/2" CIBP @ 13,073 on top to 13,038'. Perf Bone Springs @ 8,168'-8,173' w/4" csg gun 4 SPF & acc gals 15% HCL acid. No reaction after testing. Released 1 w/tbg. Set CIBP on wire line @ 8,060' dumped 35' cement of the control of the co	w/2'-4' flare, w/no tbg press. s 210 BW on 1" 155'-13,171', sg gun @ 4 SPF. 3' w/35' cement idized w/5,000 packer, POOH
3- 3-82 3-11-82 3-17-82	Perf Lower Morrow 13,484'-13,493' w/4 SPF, GTS in 30 min water to surface in 33 min. On 1" choke flwd water & gas Rec 120 BW in 6 hrs. On final test flwd to pit 10-1/2 hrs choke. Set CIBP @ 13,452' in 10' tbg sub. Perf Middle Morrow 13,140', 13,143', 13,145'-13,149', 13,113,204'-13,208', 13,217'-13,220' & 13,368'-13,369' w/4" cs Tested w/no reaction after perf. Set 5-1/2" CIBP @ 13,073 on top to 13,038'. Perf Bone Springs @ 8,168'-8,173' w/4" csg gun 4 SPF & acc gals 15% HCL acid. No reaction after testing. Released 1 w/tbg. Set CIBP on wire line @ 8,060' dumped 35' cement of Preparing to abandon.	w/2'-4' flare, w/no tbg press. s 210 BW on 1" 155'-13,171', sg gun @ 4 SPF. 3' w/35' cement idized w/5,000 packer, POOH on top to 8,025'.
3- 3-82 3-11-82 3-17-82	Perf Lower Morrow 13,484'-13,493' w/4 SPF, GTS in 30 min w water to surface in 33 min. On 1" choke flwd water & gas Rec 120 BW in 6 hrs. On final test flwd to pit 10-1/2 hrs choke. Set CIBP @ 13,452' in 10' tbg sub. Perf Middle Morrow 13,140', 13,143', 13,145'-13,149', 13,113,204'-13,208', 13,217'-13,220' & 13,368'-13,369' w/4" cs Tested w/no reaction after perf. Set 5-1/2" CIBP @ 13,073 on top to 13,038'. Perf Bone Springs @ 8,168'-8,173' w/4" csg gun 4 SPF & acc gals 15% HCL acid. No reaction after testing. Released 1 w/tbg. Set CIBP on wire line @ 8,060' dumped 35' cement of Preparing to abandon.	w/2'-4' flare, w/no tbg press. s 210 BW on 1" 155'-13,171', sg gun @ 4 SPF. 3' w/35' cement idized w/5,000 packer, POOH
3- 3-82 3-11-82 3-17-82	Perf Lower Morrow 13,484'-13,493' w/4 SPF, GTS in 30 min w water to surface in 33 min. On 1" choke flwd water & gas Rec 120 BW in 6 hrs. On final test flwd to pit 10-1/2 hrs choke. Set CIBP @ 13,452' in 10' tbg sub. Perf Middle Morrow 13,140', 13,143', 13,145'-13,149', 13,113,204'-13,208', 13,217'-13,220' & 13,368'-13,369' w/4" cs Tested w/no reaction after perf. Set 5-1/2" CIBP @ 13,073 on top to 13,038'. Perf Bone Springs @ 8,168'-8,173' w/4" csg gun 4 SPF & acc gals 15% HCL acid. No reaction after testing. Released 1 w/tbg. Set CIBP on wire line @ 8,060' dumped 35' cement of Preparing to abandon.	w/2'-4' flare, w/no tbg press. s 210 BW on 1" 155'-13,171', sg gun @ 4 SPF. 3' w/35' cement idized w/5,000 packer, POOH on top to 8,025'.
3- 3-82 3-11-82 3-17-82	Perf Lower Morrow 13,484'-13,493' w/4 SPF, GTS in 30 min w water to surface in 33 min. On 1" choke flwd water & gas Rec 120 BW in 6 hrs. On final test flwd to pit 10-1/2 hrs choke. Set CIBP @ 13,452' in 10' tbg sub. Perf Middle Morrow 13,140', 13,143', 13,145'-13,149', 13,113,204'-13,208', 13,217'-13,220' & 13,368'-13,369' w/4" cs Tested w/no reaction after perf. Set 5-1/2" CIBP @ 13,073 on top to 13,038'. Perf Bone Springs @ 8,168'-8,173' w/4" csg gun 4 SPF & acc gals 15% HCL acid. No reaction after testing. Released w/tbg. Set CIBP on wire line @ 8,060' dumped 35' cement of the performation above is true and complete to the best of my knowledge and belief. J.R. Hughes TILLE Dist. Drilling Supt.	w/2'-4' flare, w/no tbg press. s 210 BW on 1" 155'-13,171', sg gun @ 4 SPF. 3' w/35' cement idized w/5,000 packer, POOH on top to 8,025'.