

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPLYN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A (Re-Entry)		7. Unit Agreement Name
Name of Operator Yates Petroleum Corporation		8. Farm or Lease Name Record "YW"
Address of Operator 207 South 4th St., Artesia, NM 88210		9. Well No. 1
Location of Well UNIT LETTER F, 1980 FEET FROM THE North LINE AND 2180 FEET FROM THE West LINE, SECTION 25 TOWNSHIP 19S RANGE 35E NMPM.		10. Field and Pool, or: wildcat North Pearl
11. Elevation (Show whether DF, RT, GR, etc.) 3678' GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER Set CIBP, Perforate & test Queen, P&A <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-2-85 Set CIBP at 10275' w/35' cement cap. Set CIBP at 8390' w/35' cement cap. Set CIBP at 6425' w/35' cement cap.  
10-3-85 Perforated 5020-23' and 5055-58' w/10 .42" holes  
Acidized perfs 5020-58' w/1500 gals 7½% NEFE acid with 15 ball sealers.  
10-9-85 Verbal permission obtained from Mr. Jerry Sexton, NMOCD, Hobbs, 10-9-85 to plug and abandon well.  
10-14-85 PLUGGED AND ABANDONED WELL AS FOLLOWS:  
Set CIBP at 4800' with wireline cement plug at 4800', with 105 sx Class "C" Neat. Top of cement at 4225' (80' above stub at 4305'). Plug #2 - 1768-1641' with 50 sx Class "C" Neat (100' plug across Rustler at 1768'). Plug #3 - 32'-Surface plug with 42 sx Class "C" Neat. Set dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Guadalupe D. Daddett TITLE Production Supervisor DATE 10-15-85  
APPROVED BY Style F. Turnaciff TITLE OIL & GAS INSPECTOR DATE JAN 6 - 1986  
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
OCT 17 1985  
O.C.D.  
HOBBS OFFICE