

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P.O. Box 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.
------------------------------

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-1011 FOR SUCH PROPOSALS.)

XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX  
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX  
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX

OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input type="checkbox"/>	Dry Hole <input type="checkbox"/>
-----------------------------------	-----------------------------------	--------------------------------	-----------------------------------

7. Unit Agreement Name
------------------------

Name of Operator
Read & Stevens, Inc.

8. Farm or Lease Name
-----------------------

Address of Operator
P.O. Box 1518, Roswell, NM 88201

9. Well No.
-------------

Location of Well
------------------

10. Field and Pool, or Wildcat
--------------------------------

UNIT LETTER <u>P</u> . <u>330</u> FEET FROM THE <u>East</u> LINE AND <u>330</u> FEET FROM THE <u>South</u> LINE. SECTION <u>7</u> TOWNSHIP <u>17S</u> RANGE <u>37E</u> NMPM
---

Midway Abo Und.
-----------------

5. Elevation (Show whether DF, RT, GR, etc.)
3791.6' GL

12. County	XXXXXXXXXXXXXXXXXXXX
Lea	XXXXXXXXXXXXXXXXXXXX

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK	<input type="checkbox"/>	PLUG AND ABANDON	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		<input type="checkbox"/>
OTHER	<input type="checkbox"/>		<input type="checkbox"/>

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>		<input type="checkbox"/>
OTHER	<input type="checkbox"/>		<input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PBTD @ 5150' w/CIBP and 35' cmt, perms @ 4140'-4164', 2 shots/'.

- 1) Set 15sx cmt 100' over perms, TOC @ 3950', spot mud between plugs.
- 2) Cut csg @ 3500', pull csg, spot 50sx Class "C" cmt, 50' in 5 1/2" csg, 50' in 8 5/8" csg, & 50' in open hole, 120', from 3550' to 3430'.
- 3) Spot 100' plug, 35sx Class "C" at the top of the salt, 2040' to 2150'.
- 4) Spot 10sx Class "C" at surface w/4 1/2" marker.
- 5) Oil Conservation Commission Representative was on location to witness plugging.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. Stobly TITLE Drilling & Production Manager DATE 8-2-82

APPROVED BY Ronald M. Eastberg TITLE OIL & GAS INSPECTOR DATE JAN 24 1983

CONDITIONS OF APPROVAL, IF ANY: