CONDITIONS OF APPROVAL, IF ANY:

NERGY AND MINERALS DEPARTMENT	Form C-103
O. OF COPIES RECEIVED OIL CONSERVATION DIVISION	Revised 10-1-78
DISTRIBUTION P.O. Box 2088	
ANTA FE SANTA FE, NEW MEXICO 87501	5a. Indicate Type of Lease
ILE	State Fee X
.s.g.s	
AND OFFICE	5. State Oil & Gas Lease No.
PERATOR	-
SUNDRY NOTICES AND REPORTS ON WELLS	xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-1011 FOR SUCH PROPOSALS.)	<u> </u>
OIL GAS	7. Unit Agreement Name
WELL OTHER Dry Hole	<u>-</u>
Name of Operator	8. Farm or Lease Name
	Midway "7"
Read & Stevens, Inc.	9. Well No.
Address of Operator	1
P.O. Box 1518, Roswell, NM 88201	10. Field and Pool, or Wildcat
Location of Well	TO. Flero and root, of Wildeat
UNIT LETTER P . 330 FEET FROM THE East LINE AND 330 FEET FROM	Midway Abo Und.
THE South LINE SECTION 7 TOWNSHIP 175 RANGE 37E NMPM	**************************************
xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx	12. County XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
AXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	Lea XXXXXXXXXXXXXXXXX
Check Appropriate Box To Indicate Nature of Notice, Report or Other	
NOTICE OF INTENTION TO: SUBSEQUENT REF	
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.	ALTERING CASING
PULL OR ALTER CASING CHANGE LEAR OTHER OTHER	PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER OTHER	
PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER Scribe Proposed or Completed Operations(Clearly state all pertinent details, and give	
PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER OTHER Scribe Proposed or Completed Operations(Clearly state all pertinent details, and give	pertinent dates, including esti-
PULL OR ALTER CASING OTHER CASING TEST AND CEMENT JOB OTHER Scribe Proposed or Completed Operations(Clearly state all pertinent details, and give ted date of starting any proposed work) SEE RULE 1103.	pertinent dates, including esti-
PULL OR ALTER CASING OTHER CASING TEST AND CEMENT JOB OTHER Scribe Proposed or Completed Operations(Clearly state all pertinent details, and give ted date of starting any proposed work) SEE RULE 1103. PBTD @ 5150' w/CIBP and 35' cmt, perfs @ 4140'-4164', 2 shots/ 1) Cut csg @ 3500', pul csg, spot 55sx Class "C" cmt, 50' in 5 1.	pertinent dates, including esti- '. /2" csg, 50' in 8 5/8" csg, & 50'
PULL OR ALTER CASING OTHER CASING TEST AND CEMENT JOB OTHER Scribe Proposed or Completed Operations(Clearly state all pertinent details, and give ted date of starting any proposed work) SEE RULE 1103. PBTD @ 5150' w/CIBP and 35' cmt, perfs @ 4140'-4164', 2 shots/ 1) Cut csg @ 3500', pul csg, spot 55sx Class "C" cmt, 50' in 5 1, in open hole, 150', from 3550' to 3400'.	pertinent dates, including esti- '. /2" csg, 50' in 8 5/8" csg, & 50'
CASING TEST AND CEMENT JOB OTHER Scribe Proposed or Completed Operations(Clearly state all pertinent details, and give ted date of starting any proposed work) SEE RULE 1103. PBTD @ 5150' w/CIBP and 35' cmt, perfs @ 4140'-4164', 2 shots/ 1) Cut csg @ 3560', pul csg, spot 55sx Class "C" cmt, 50' in 5 1, in open hole, 150', from 3550' to 3400'. 2) Spot 100' plug, 25sx Class "C" at the top of the salt, 2050' to	pertinent dates, including est '. /2" csg, 50' in 8 5/8" csg, & 5
CASING TEST AND CEMENT JOB OTHER Scribe Proposed or Completed Operations(Clearly state all pertinent details, and give ited date of starting any proposed work) SEE RULE 1103. PBTD @ 5150! w/CIBP and 35! cmt, perfs @ 4140!-4164!, 2 shots/ 1) Cut csg @ 3500!, pul csg, spot 55sx Class "C" cmt, 50! in 5 1, in open hole, 150!, from 3550! to 3400!. 2) Spot 100! plug, 25sx Class "C" at the top of the salt, 2050! to	pertinent dates, including esti . /2" csg, 50' in 8 5/8" csg, & 50 o 2150'.
OTHER CASING TEST AND CEMENT JOB OTHER Scribe Proposed or Completed Operations (Clearly state all pertinent details, and give ted date of starting any proposed work) SEE RULE 1103. PBTD @ 5150' w/CIBP and 35' cmt, perfs @ 4140'-4164', 2 shots/ 1) Cut csg @ 3560', pul csg, spot 55sx Class "C" cmt, 50' in 5 1, in open hole, 150', from 3550' to 3400'. 2) Spot 100' plug, 25sx Class "C" at the top of the salt, 2050' to 3) Spot 10sx Class "C" at surface w/4 1/2" marker. 4) Oil Conservation Commission will be notified before plugging @	pertinent dates, including esti- 1. /2" csg, 50' in 8 5/8" csg, & 50 0 2150'.
OTHER CASING TEST AND CEMENT JOB OTHER CASING TEST AND CEMENT JOB OTHER Scribe Proposed or Completed Operations(Clearly state all pertinent details, and give ited date of starting any proposed work) SEE RULE 1103. PBTD @ 5150' w/CIBP and 35' cmt, perfs @ 4140'-4164', 2 shots/ 1) Cut csg @ 3560', pul csg, spot 55sx Class "C" cmt. 50' in 5 1, in open hole, 150', from 3550' to 3400'. 2) Spot 100' plug, 25sx Class "C" at the top of the selt, 2050' to 3) Spot 10sx Class "C" at surface w/4 1/2" marker. 4) Oil Conservation Commission will be notified before plugging @ hereby certify that the Information above is true and complete to the best of my known.	pertinent dates, including esti- '. /2" csg, 50' in 8 5/8" csg, & 50 o 2150'. 505-393-6161.
OTHER CASING TEST AND CEMENT JOB OTHER Scribe Proposed or Completed Operations (Clearly state all pertinent details, and give ted date of starting any proposed work) SEE RULE 1103. PBTD @ 5150' w/CIBP and 35' cmt, perfs @ 4140'-4164', 2 shots/ 1) Cut csg @ 3500', pul csg, spot 55sx Class "C" cmt, 50' in 5 1, in open hole, 150', from 3550' to 3400'. 2) Spot 100' plug, 25sx Class "C" at the top of the salt, 2050' to 3) Spot 10sx Class "C" at surface w/4 1/2" marker. 4) Oil Conservation Commission will be notified before plugging @	pertinent dates, including esti- '. /2" csg, 50' in 8 5/8" csg, & 50 o 2150'. 505-393-6161.
OTHER CASING TEST AND CEMENT JOB OTHER Scribe Proposed or Completed Operations (Clearly state all pertinent details, and give ted date of starting any proposed work) SEE RULE 1103. PBTD @ 5150! w/CIBP and 35! cmt, perfs @ 4140!-4164!, 2 shots/ 1) Cut csg @ 3500!, pull csg, spot 55sx Class "C" cmt, 50! in 5 1, in open hole, 150!, from 3550! to 3400!. 2) Spot 100! plug, 25sx Class "C" at the top of the selt, 2050! to 3) Spot 10sx Class "C" at surface w/4 1/2" marker. 4) Oil Conservation Commission will be notified before plugging @ hereby certify that the Information above is true and complete to the best of my kno SIGNED TITLE Drilling & Production Manage	pertinent dates, including esti- '. /2" csg, 50' in 8 5/8" csg, & 50' o 2150'. 505-393-6161. wledge and belief. r DATE 7-19-82
OTHER CASING TEST AND CEMENT JOB OTHER CASING TEST AND CEMENT JOB OTHER Scribe Proposed or Completed Operations(Clearly state all pertinent details, and give ted date of starting any proposed work) SEE RULE 1103. PBTD @ 5150' w/CIBP and 35' cmt, perfs @ 4140'-4164', 2 shots/ 1) Cut csg @ 3500', pul csg, spot 55sx Class "C" cmt, 50' in 5 1, in open hole, 150', from 3550' to 3400'. 2) Spot 100' plug, 25sx Class "C" at the top of the salt, 2050' to 3) Spot 10sx Class "C" at surface w/4 1/2" marker. 4) Oil Conservation Commission will be notified before plugging @ hereby certify that the Information above is true and complete to the best of my kno	pertinent dates, including esti- '. /2" csg, 50' in 8 5/8" csg, & 50' o 2150'. 505-393-6161.