

DEPARTMENT OF THE INTERIOR U.S. GEOLOGICAL SURVEY
 COMMISSION
 Drawer DD
 Artesia, NM 88210

NM 077004

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER Dry Hole	7. UNIT AGREEMENT NAME -----
2. NAME OF OPERATOR Walter W. Krug D.B.A. Wallen Prod. Co.	8. FARM OR LEASE NAME Wallen Federal 19
3. ADDRESS OF OPERATOR P.O. Box 1960 Midland, Texas 79702	9. WELL NO. 2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) 990' FWL & 1650' FSL	10. FIELD AND POOL, OR WILDCAT South Tonto Yates-⁷ River
14. PERMIT NO. -----	11. SEC., T., R., M., OR ELE. AND SURVEY OR AREA Sec. 19, T19S, R33E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) GR 3602	12. COUNTY OR PARISH Lea
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

On 3/9/82 we propose to plug the above well in the following manner:

1. Fill the hole from TD of 3185' to 2900'; which is 53' up inside the 7" salt string. Leave plug set over night and tag in the morning.
2. Fill from bottom plug to surface with 9½# fresh H₂O mud.
3. Set a 150' plug from top of Rustler to top of salt (approx. 1200' to 1350').
4. Put a 15 sx plug in top of casing with well marker.

RECEIVED
MAR 10 1982

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO
ACCEPTED FOR RECORD

18. I hereby certify that the foregoing is true and correct

SIGNED Walter W. Krug TITLE Engineer

(This space for Federal or State office use)

APPROVED BY _____
 CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE 3/3/82

MAY 8 1982

U.S. GEOLOGICAL SURVEY
 ROSWELL, NEW MEXICO

RECEIVED
MAY 3 1982
O.C.D.
HOBBS OFFICE