ENERGY AND MINERALS DEPARTMENT	
JIL CONSERVATION DIVISIO	
DISTRIBUTION P. O. BOX 2038	Form C-103
SANTA FE SANTA FE NEW MEXICO 8750	Revised 10-1-
U.S.G.S.	Su. Insteate Type of Lease
LAND OFFICE	State X Fee
OPERATOR	5. State Oil & Gas Leave No.
	L-6939
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSILS TO GALLE ON TO DEEPEN GA PLUG SICK TO A DIFFERENT RESERVOID. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL A GAS WELL OTHER.	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Farm or Lease Name State IV
3. Address of Operator	9. Well Ho.
P. O. Box 68, Hobbs, New Mexico 88240	1
4. Location of Well UNIT LETTER 2310 FEET FROM THE South LINE AND 660 FEET FROM	10. Field and Pool, or Wildcat Wildcat San Andres
THE West LINE, SECTION 31 TOWNSHIP 17-S RANGE 36-E HMP	://///////////////////////////////////
3882.9	12. County
Check Appropriate Box To Indicate Nature of Notice, Report or O	Lea AMM
NOTICE OF INTENTION TO:	ther Data
	TREPORT OF:
PERFORM REMEDIAL WORK	ALTERING CASING
PULL OF ALTER CASING	PLUG AND ABANDONMENT
CHANGE PLANS CASING TEST AND CEMENT JOB	
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includin work) SEE RULE 1903.	g estimated date of starting any proposi
· · · · · · · · · · · · · · · · · · ·	
Moved in service unit 7-14-82. Ran CIBP set at 9425'. Pressure tested O.K. Capped with 35' of cement. Perforated Abo interval 7546'-52' with and packer. Tubing landed at 7458' and packer set at 7359'. Swab test 42 barrels of load water. Acidized well with 2000 gallons 15% NE HCL ac 46 barrels of brine water. Swab tested 18 hours. Recovered 220 barrels out service unit 7-20-82. SI. Moved in service unit 8-3-82. Pulled pac CIBP and set at 7400'. Tested to 500 PSI. Tested OK. Capped with 35' of San Andres intervals 5152'-64' with 5172'-86' with 4 JSPF. Ran tubing ar set at 4950' and tailpipe landed at 5050'. Swab tested 9 hours. Recover Acidized well with 5000 gallons 15% NEFE HCL. Flushed with 32 barrels of 20 hours. Recovered 40 barrels of water. Currently swab testing.	2 JSPF. Ran tubing hours. Recovered d. Flushed with of new water. Moved ker and tubing. Ran f cement. Perforated d packer. Packer ed 2 barrels water. water. Swab tested
and packer. Tubing landed at 7458' and packer set at 7359'. Swab test 42 barrels of load water. Acidized well with 2000 gallons 15% NE HCL ac 46 barrels of brine water. Swab tested 18 hours. Recovered 220 barrels out service unit 7-20-82. SI. Moved in service unit 8-3-82. Pulled pace CIBP and set at 7400'. Tested to 500 PSI. Tested OK. Capped with 35' of San Andres intervals 5152'-64' with 5172'-86' with 4 JSPF. Ran tubing ar set at 4950' and tailpipe landed at 5050'. Swab tested 9 hours. Recover	2 JSPF. Ran tubing hours. Recovered d. Flushed with of new water. Moved ker and tubing. Ran f cement. Perforated d packer. Packer ed 2 barrels water. water. Swab tested
and packer. Tubing landed at 7458' and packer set at 7359'. Swab test 42 barrels of load water. Acidized well with 2000 gallons 15% NE HCL ac 46 barrels of brine water. Swab tested 18 hours. Recovered 220 barrels out service unit 7-20-82. SI. Moved in service unit 8-3-82. Pulled pace CIBP and set at 7400'. Tested to 500 PSI. Tested OK. Capped with 35' of San Andres intervals 5152'-64' with 5172'-86' with 4 JSPF. Ran tubing ar set at 4950' and tailpipe landed at 5050'. Swab tested 9 hours. Recover Acidized well with 5000 gallons 15% NEFE HCL. Flushed with 32 barrels of 20 hours. Recovered 40 barrels of water. Currently swab testing.	2 JSPF. Ran tubing hours. Recovered d. Flushed with of new water. Moved ker and tubing. Ran f cement. Perforated d packer. Packer ed 2 barrels water. water. Swab tested

AIGNED	treeman	Accict Admin America	
and the second sec	7	Assist. Admin. Analyst	BATE 8-11-82
APPROVED BY		71766	AUGIO 1982