ENERGY AND MINERALS DEPARTMENT	
OIL CONSERVATION DIVISIC .	
DISTRIBUTION P. O. BOX 2088	Fan. 2.222
SANTA FE, NEW MEXICO 87501	Form C-103 Revised 10-
U.S.G.S.	5a. Indicate Type of Lease
LAND OFFICE OPERATOR	State X Foe
	5. State Off & Gas Leave No.
CHADDA	L-6939
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO GRILL OR TO DEEPEN OR PLUE SACK TO A DIFFERENT RESERVOIR. 1.	
OIL GAS WELL OTHER-	7. Unit Agreement Name
Amoco Production Company	8. Farm or Lease Name State IV
3. Address of Operator	9. Well No.
P. O. Box 68, Hobbs, N.M. 88240	1 .
UNIT LETTER L 2310 South 660	10. Field and Pool, or Wildcat Wildcat Abo
West LINE, SECTION 31 TOWNSHIP 17-S RANGE 36-E	
15. Elevation (Show whether DF, RT, GR, etc.) 3882.9 GL	Lea
Check Appropriate Box To Indicate Nature of Notice, Report of	- O-l - D
	UENT REPORT OF:
PERFORM REMEDIAL WORK X	ALTERING CASING
TEMPERANTLY ADAHON COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND CEMENT JCB	
OTHER	
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1703.	luding estimated date of starting any propo
Propose to abandon the Strawn interval 11,518'-30' and test	the Alexander
9484'-9506' per the following:	the ADO Interval
Pull tubing and packer. Run cast iron bridge plug, set at	11 4501 1
35' of cement. Run second cast iron bridge plug, set at 99	11,450 and cap with
psi. (This will isolate Wolfcamp perfs which have already	book and test to 500
Perforate Abo interval 9484'-9506' with 2 SPF. Run in hole	been squeezed.)
packer, and tailpipe. Set packer at 9300', tailpipe to be	landed at 02001
Swab test well.	randed at 9390.
•	
P+4-NMOCD,H 1-HOU 1-DMF 1-W. STAFFORD, HOU	
·	

Assistant Admin. Analyst 6-17-82 Orig. Signed by
Les Clements

CONDITIONS ON OIL BAGGER LIDED.ANY:

.LUN 18 1982

JUN 18 1982