orm 2160 5	P. C 12 17		Form approved.
Corm 3160-5 UNITED STATES (ovember 1983) Formerly 9-331) DEPARTMENT OF THE INTERIOR		SUBMIT IN TRIPLICATES Of ther instructions on re-	Budget Bureau No. 1004-0135 Expires August 31, 1985
, , ,	RIMENT OF THE INTERIOR REAU OF LAND MANAGEMENT	OL AGERG BIGG)	5. LEASE DESIGNATION AND SERIAL NO.
SUNDRY NOTICES AND REPORTS ON WELLS			NM 077004 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
(Do not use this form for I	POINCES AND REPORTS Corposals to drill or to deepen or plug bandling for PERMIT—" for such pro-	ck to a different reservoir.	
OIL GAS			7. UNIT AGREEMENT NAME
WELL LY WELL OTHER . NAME OF OPERATOR			8. FARM OR LEASE NAME
Harvey E. Yates Company			Federal 19
ADDRESS OF OPERATOR			9. WELL NO.
P.O. Box 1933, Roswell, New Mexico 88202 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*			#1 10. FIELD AND POOL, OR WILDCAT
See also space 17 below.) At surface	60' FSL & 1980' FWL	·	Undesignated Bone Spring 11. BEC., T., E., M., OR BLE. AND SURVEY OR ARBA Sec. 19, T19S, R33E
. PERMIT NO.	15. ELEVATIONS (Show whether Dr.	RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
30-025-27730	3602.1 GL		Lea NM
	Appropriate Box To Indicate No	ature of Notice Report or C	
	INTENTION TO:		BNT RBPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other)	of multiple completion on Well
(Other)	D OPERATIONS (Clearly state all pertinent	Completion or Recomple	etion Report and Log form.) including estimated date of starting any
proposed work. If well is d nent to this work.) •	irectionally drilled, give subsurface locati	ons and measured and true vertica	I depths for all markers and gones perti-
	gals 15% NEFE.	u w/250 gal 15% NEFE	acid followed w/450 gals sa
	gals 15% NEFE.		
-20-89 Acidz w/5000	gals 20% NEFE & overflu		
	perfs 9787-9895 (OA), a	cidz w/2700 gals 7½%	SRA
-24-89 Perf & acidz			
-24-89 Perf & acidz -28-89 Frac'd w/89,	000 gals WF 40 & 131,100	# 16-20 carbolite	
-24-89 Perf & acidz -28-89 Frac'd w/89,	000 gals WF 40 & 131,100	# 16-20 carbolite	
-24-89 Perf & acidz -28-89 Frac'd w/89,	000 gals WF 40 & 131,100	# 16-20 carbolite	
-24-89 Perf & acidz -28-89 Frac'd w/89,	000 gals WF 40 & 131,100	# 16-20 carbolite	
-24-89 Perf & acidz -28-89 Frac'd w/89,	000 gals WF 40 & 131,100	# 16-20 carbolite	
-24-89 Perf & acidz -28-89 Frac'd w/89,	000 gals WF 40 & 131,100	# 16-20 carbolite	
-24-89 Perf & acidz -28-89 Frac'd w/89, -11-89 Put on prod.	000 gals WF 40 & 131,100 11-11-89	# 16-20 carbolite A a d. Manager/Engineer	DATE 11-14-89
-24-89 Perf & acidz -28-89 Frac'd w/89, -11-89 Put on prod.	000 gals WF 40 & 131,100 11-11-89	Aores	11 14 00