

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT - " for such proposals

Lease Designation and Serial No.

NM-94191

5. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Santa Fe Energy Resources, Inc.

3. Address and Telephone No.

550 W. Texas, Suite 1330, Midland, TX 79701 (915) 687-3551

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

(B), 660' FNL and 1980' FEL, Sec. 14, T-18S, R-32E

8. Well Name and No.

Shinnery 14
Federal #9

9. API Well No.

30-025-27769

10. Field and Pool, or exploratory Area

Undesignated

11. County or Parish, State

Lea Co., NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

2/19/97: MIRU. Clean out cellar, ND WH, NU BOP. Released pkr, spot 65 bbls drlg mud. POOH w/ tubing. RIH w/ WL and set CIBP @ 3800'. Load hole w/ 23 BW, test to 600 psi for 10 min., okay. RIH and dump bailed 35' cement on top of CIBP. POOH.

2/20/97: Weld on 5-1/2" csg pull nipple, rel csg slips, work casing. RIH w/ WL and tag cmt at 3765'. Pulled up to 2007' and cut casing off. POOH w/ 69 jts 5-1/2" 17.0# csg. RIH w/ tbq to 3369', mix 10 sx 95 salt gel mud, pump 60 sx C1 "C" cmt. Spotted cmt at 4467'-3180'.

2/21/97: RIH & tag TOC @ 2780'. POOH & LD tbq. RIH and pumped 200 sx C1 "C" plug at 1204' (est top of plug at 584').

2/22/97: RIH & tagged TOC @ 568'. RIH and pumped 25 sx C1 "C" surface plug. RD, cut 9-5/8" WH off. Installed dry hole marker. Well P&A'd.

Approved by _____ of the well owner,
Label _____, _____, _____
surface location is completed.

14. I hereby certify that the foregoing is true and correct

Signed

Title Sr. Production Clerk

Date 03/11/97

(This space for Federal or State office use)

Approved by

JORIG. SGLA R. GLASS

Title

PETROLEUM ENGINEER

Date

MAR 17 1997

Conditions of approval, if any: