## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
NO. OF COMIES RECEIVED			
DISTRIBUTION			
SANTA FE			
FILE			
U.S.G.S.			
LAND OFFICE			
DPERATOR			

NO. 47 COPIES RECEIVED	OIL CONSERVA		Form C-103
DISTRIBUTION	P. O. BOX 2088		Revised 19-1-78
SANTA FE SANTA FE, NEW MEXICO 87501		5a. Indicate Type of Lease	
FILE			
U.S.G.S.			State X Fee
LAND OFFICE	•		5. State Oil & Gas Lease No.
DPERATOR	·		A-4096
A. 1. 1. P. P.	NOTICES AND DEPORTS ON	WELLS	
SUNDRY	NOTICES AND REPORTS ON VOSALS TO DRILL OR TO DEEPEN OR PLUG BADEN FOR PERMIT - " (FORM C-101) FOR SUCH	MILLS CX TO A DIFFERENT RESERVOIR. (PROPOSALS.)	
USE "APPLICATIO	IN FOR PERMIT - PORM COLUMN TOR SUCH		7. Unit Agreement Name
. OIL 🔻 GAS			
WELL (A) WELL L.	OTHER-		8. Farm or Lease Name
. Name of Operator			New Mexico "DD" State
Exxon Corporation			9. Weil No.
. Address of Operator			1
P. O. Box 1600, Midlan	d, Texas 79702		10. Field and Pool, or Wildcat
Location of Well			Coharb
NT	660 FEET FROM THE South	LINE AND 1980 PEET FI	OM CTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTT
•			
THE West LINE, SECTION 4 TOWNSHIP 195 RANGE 35E NMPM.		··· (	
THE WEST LINE, SECTIO	N TOWNSHIP		
mmmm	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
			Lea
	7////	Calling Domain	Other Data
	Appropriate Box To Indicate N	ature of Notice, Report of	OUICE DALA
NOTICE OF IN		SUBSEQUE	ENT REPORT OF:
		, <u>-</u>	۲
PERFORM REMEDIAL WORK	PLUG AND ABÀNDON	REMEDIAL WORK	ALTERING CASING
		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS	CASING TEST AND CEMENT JOS X	
PULL OR ALTER CASING		отнея	
	. $\square$		
OTHER			
An Desertha Proposed or Completed Or	perations (Clearly state all pertinent det	ails, and give pertinent dates, inclu	ding estimated date of starting any propose
work) SEE RULE 1103.			
Drilled 7 7/8" hole to	10,800	10 E0014+1 DV +1	1 at 7060 1st
Ran 266 jts 10,569 5	1/2" 15.5, 17# csg set at	10,582', With DV tool	Lat /707. ISL
stage cmt w/150 sx TIN	J. wt. 11.8. 4% gel 1/2%	halad 9, $3\#/sk$ gil, Ta	alled M/200 SK CI
"H" wt. 16, plug down	4:00 p.m. 8-3-82. Pump	2nd stage w/1660 sx Tl	LW, 4% gel, Tailed
/100 or CT "U" Noat	Circ cmt to surface		
Plus Die NOT Bump. DV to	ool open stop pumping at	3:42 a.m. 8-4-82. He	ld 2000# on cmt. WOC
True bis Dump, DV Co			
masted 5 1/9!! ass at (	9:30 a.m. 8-11-82 w/2000#	-Held OK	
rested 5 1/2 Csg at 3	, a.m. o ii oz w/2000		
Preparing to Perf.			
	u		
	•		
	•		
	n above is true and complete to the best	of my knowledge and belief.	
18. I hereby certify that the informatio	n above is true and complete to the best		
k. 10/ X	_	Sr. Administrator	9/3/82
W. J. X bu	TITLE	or. Auministrator	DATE
SIGNED			
		A	mots