

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.	30-025-27788
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		New Mexico CX State	
2. Name of Operator Nearburg Producing Company		8. Well No. 2	
3. Address of Operator 419 W. Cain		9. Pool name or Wildcat Shoe Bar Morrow	
4. Well Location Unit Letter <u>G</u> : 1980 Feet From The North Line and 1980 Feet From The East Line			
Section <u>2</u> Township <u>17S</u> Range <u>35E</u> NMPM Lea County		10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set C.I.B.P. @ 12,410'. Cap with 35' cement
- Circulate hole with mud laden fluid
- Spot cement plug from 10324' - 10,224'
- Spot cement plug from 7600' - 7500'
- Spot 8 5/8" shoe plug from 5066' - 4966'
- Stretch, cut, and pull +2800' 5 1/2" casing
- Spot cement plug from 2850' - 2750'. Tag
- Stretch, cut, and pull + 1000' 8 5/8" casing
- Spot cement plug from 1050' - 950'. Tag
- Set surface. Cut off wellhead. Erect dry hole marker. Clean location.

* Mud laden fluid between all plugs

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Scott Kimbrough TITLE Manager DATE 10/1/96

TYPE OR PRINT NAME Scott Kimbrough TELEPHONE NO. 397-4186

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE OCT 18 1996

CONDITIONS OF APPROVAL, IF ANY: