

MID-AMERICA #3 ✓

P&A, OTHER

2/ 5-1/2" CS @ 13680/ PB 11500/ PN 638910/ LA RICA/ LEA/ NM/ WI .66

PFS: 10184-518(BONE SPRING)

12/17/91 ✓

TIH W/2-7/8" WS OE TO 10000'/ DISPL HOLE W/120 BBLS 10# MUD LADEN FLUID/
SDFN/ PREP TO FINISH CIRC HOLE & CUT CSG/

MID-AMERICA #3 ✓

P&A, OTHER

3/ 5-1/2" CS @ 13680/ PB 11500/ PN 638910/ LA RICA/ LEA/ NM/ WI .66

PFS: 10184-518(BONE SPRING)

12/18/91 ✓

FIN DISPL HOLE W/10# MUD LADEN FLUID/ POH W/WS/ ND BOP & WELLHEAD/ PU ON
5-1/2" CSG/ COLLAR BROKE OFF OF SPEAR/ COULD NOT WORK CSG OFF OF SLIPS/ SD
FOR SPEAR REPAIR/ PREP TO CUT & PULL CSG/

MID-AMERICA #3 ✓

P&A, OTHER

4/ 5-1/2" CS @ 13680/ PB 11500/ PN 638910/ LA RICA/ LEA/ NM/ WI .66

PFS: 10184-518(BONE SPRING)

12/19/91 ✓

RU SPEAR & LATCH CSG/ REMOVE WH SLIPS/ RU WL & CUT CSG @ 4510'/ WORK
CSGLOOSE & POH, LD 1 JT 5-1/2" CSG/ SD FOR RIG REPAIR/ SDFN/ PREP TO FIN POH
LD CSG/

MID-AMERICA #3 ✓

P&A, OTHER

5/ 5-1/2" CS @ 13680/ PB 11500/ PN 638910/ LA RICA/ LEA/ NM/ WI .66

PFS: 10184-518(BONE SPRING)

12/20/91 ✓

POH, LD 101 JTS 5-1/2" CSG/ RIH W/2-7/8" WS OE TO 4550'/ SPOT 75 SX CL "C"
CMT PLUG/ POH TO 4000'/ SDFN/ PREP TO TAG PLUG/

MID-AMERICA #3 ✓

P&A, OTHER

6/ PB 3' BGL/ PN 638910/ LA RICA/ LEA/ NM/ WI .66

12/21/91 ✓

*** FINAL REPORT ***

TIH W/2-7/8" WS/ TAG TOC 4330/ TOH W/2-7/8" WS/ RIH W/WL PERF GUN & PERF 4
HOLES @ 600/ ATT TO PUMP INTO HOLES W/2000# W/NO SUCC/ TIH W/2-7/8" WS OE TO
620/ SPOT 50 SX CMT @ 620/ TOH W/2-7/8" WS/ SPOT 10 SX CMT 30'-SURF/ CUT OFF
CSG 3' BGL/ WELD ON 1/2" STEEL PLATE/ INST DRY HOLE MARKER/ RR 12/20/91/
WELL P&A/