

Procedure cont. Mid America State 3

8. POH w/ WS to 15'. Spot 3 sx class "C" cmt. Plug from 15' to 4' bgl. POH w/ WS.
9. RD. Cut off csg. 4' BGL. Weld on steel plate and dry hole marker. Reclaim location.  
RR.

Note: Notify NMO&GCC 24 hrs prior to beginning operations.

All calcs. based on use of class "C" cmt., w/a yield of 1.32 FT<sup>3</sup>/sk.

Displace all plug w/ 9.5 ppg mud laden fluid.